

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

DATE: 20.08.2022 (Sat)

MODEL: HYUNDAI I40

VEH NO.: SHC9000E

INSURANCE: NTUC (L/S)

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper	1		\$553.00
	Rear Bumper Reinforcement	1		\$428.40
	Rear Bumper Clip (10 pcs)	10	\$2.20	\$22.00
	Rear Bumper Side Bracket LH / RH	2	\$35.60	\$71.20
	Rear Bumper Sponge	1		\$119.50
	Rear Bumper Under Cover	1		\$228.00
	Rear Bumper Reflector LH / RH	2	\$32.00	\$64.00
	<b>SPARE PARTS SUB TOTAL</b>			\$ 1,486.10
	<b>LESS 20%</b>			\$ 297.22
	<b>DISCOUNTED TOTAL</b>			\$ 1,188.88
	Reverse Sensor	1		\$135.70
	<b>SUB S/NETT</b>			\$135.70
	<b>LESS 10%</b>			\$13.57
	<b>S/NETT TOTAL</b>			\$122.13
	Rear Fender Adv. Sticker LH / RH	2	\$ 100.00	\$ 200.00 NETT
	Rear Bumper Adv. Sticker	1		\$ 50.00 NETT
	Rear Bumper Mat	1		\$ 50.00 NETT
	<b>SPARE PARTS &amp; OTHERS TOTAL</b>			\$ 1,611.01
	Panel Beating			\$ 300.00
	Spray Painting Charge			\$ 300.00
	Remove/Refix Reverse Sensor			\$ 120.00
	<b>LABOUR TOTAL</b>			\$ 720.00
	<b>ESTIMATE TOTAL</b>			\$ 2,331.01

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days.  
 4/5  
 One King  
 2/8/22  
 3pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by:

Signature:

Date: