



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8339K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	REAR BUMPER	CRACKED	503.04	503.04
1	REAR BUMPER REINFORCEMENT	NOT NECESSARY	378.32	-
1	REAR BUMPER TOW COVER	NOT NECESSARY	82.70	-
1	REAR BUMPER SIDE RETAINER LH	CUT	112.70	112.70
1	REAR BUMPER LOWER COVER	DEFORMED	654.96	654.96
1	REAR BUMPER REFLECTOR LH	NOT NECESSARY	55.00	-
1	REAR SIDE UNDER COVER	NOT NECESSARY	232.00	-
10	REAR BUMPER CLIPS @\$2.20	NECESSARY	22.00	22.00
1	REAR FENDER LH	TO REPAIR SEE LABOUR	992.04	-
1	AIR DUCT LH	NOT NECESSARY	165.10	-
1	TAIL LAMP SIDE COVER LH	NOT NECESSARY	256.00	-
1	TAIL LAMP LH UPP	CRACKED	557.90	557.90
1	TAIL LAMP LH LOW	CRACKED	570.00	570.00
	LESS 25% DISCOUNT		-1,145.44	-605.15
			3,436.32	1,815.45
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REAR BUMPER MAT (SN)	NECESSARY	50.00	50.00
1	REAR REVERSE SENSOR (SN)	NOT NECESSARY	135.70	-
1	PETROL COVER STICKER (SN)	NECESSARY	25.00	25.00
1	BOOTLID COMFORT APP (SN)	NOT NECESSARY	40.00	-
1	BOOTLID COMFORT / TEL NO STICKER (SN)	NOT NECESSARY	60.00	-
			310.70	75.00
<b><u>LABOUR</u></b>				
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF REAR FENDER LH.		1,050.00	700.00
	SPRAY PAINTING CHARGE.		800.00	500.00
	REMOVE / REFIX UPHOLSTERY REAR.		90.00	60.00
	TUFF KOTE.	NOT NECESSARY	60.00	-

Report Ref No. NS/INC22008192/Gvce2



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	CHECK LIGHTING.		60.00	30.00
			2,060.00	1,290.00
GRAND TOTAL			5,807.02	3,180.45
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,550.00

Report Ref No. NS/INC22008192/Gvce2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.