## COMFORTDELGRO ENGINEERING PTE LTD

**REPAIR ESTIMATE\*** VEHICLE NO

MAKE

SHC8339K

**REG 30.09.2020** 

20.08.2022

MODEL **TOYOTA PRIUS G4**  CHIANG/ NTUC

Qty	Parts Description/ Labour	Unit Price	Amount
1	REAR BUMPER / CHI		
	REAR BUMPER REINFORCEMENTX ( NN		\$503.04
	REAR BUMPER TOW COVER X		\$378.3
1	REAR BUMPER SIDE RETAINER LH		\$82.70
	REAR BUMPER LOWER COVER		\$112.70
	REAR BUMPER REFLECTOR LH		\$654.90
	REAR SIDE UNDER COVER X		\$55.00
	REAR BUMPER CLIPS / 16 (		\$232.00
	REAR FENDER LH X My	\$2.20	\$22.00
	AIR DUCT LH X		\$992.04
	TAIL LAMP SIDE COVER LH X		\$165.10
	TAIL LAMP LH UPP		\$256.0
	TAIL LAMP LH LOW		\$557.9
,1	· •		\$570.0
	SUB TOTAL		\$4,581.7
	25.00%		\$1,145.4
	DISCOUNTED TOTAL		\$3,436.3
1	REAR BUMPER MAT REAR REVERSE SENSOR PETROL COVER STICKER  MC		
	REAR REVERSE SENSOR X		\$50.0
	PETROL COVER STICKER / MCC		\$135.7
	BOOTLID COMFORT APP	,	\$25.0
	. ( )	$\sim$	\$40.0
1	BOOTLID COMFORT/TEL NO STICKER X		\$60.0
			\$310.7
	Labour Charge		
	Panel Beating	7.	Ć1 050 0
	Spray Painting Charge	low	\$1,050.0
	Remove/Refix Upholstery rear	Sae	\$800.0
	Tuff Kote	4060	\$90.0
	Check Lighting	20	\$60.0
	TOTAL LABOUR	40	\$60.0
	TOTAL LABOUR		\$2,060.0
	EST <u>IMATE FOTAL</u>	its hence notify	\$4,464.6
	the Repairer of the	following:	
	This is an initial estimate based on a visual inspection of the	above yelicle. The final repair qua	intum will
	be prepared after the vehicle is surveyed by almotor Survey	or appointed by the insurance com	

No illegal modifications, as a way.

Supplement of the surveyed and is subject to the approximation of the comparison. ce Company

Acti