12/30/22, 2:57 PM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Allianz Insurance Singapore Pte. Ltd. **Our File No:** CS/AIS22008193/KCY3M4

79 Robinson Road #09-01 Date: 30/12/2022 Singapore 068897

**REFERENCE** 

Insured/Claimant: SK CATERING EVENTS PTE LTD Policy No: SPMF1000000508

Date of Loss: 16/08/2022 Nature of Claim: OD Claim No: SKCEAISCL2022-00001

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **GBF4222U** 

Make & Model: TOYOTA DYNA 150 MANUAL, 3.0 D (M) 1KD2616092 Engine No:

JTFAT35YX0K206465 Reg. Date: 11/10/2016 (Man. Year: 2016) Chassis No:

Colour: White Odometer: 262824 km

**Engine Capacity:** 2982 cc

Market Value/New Car Price:

S\$48.000.00

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): General Condition: Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195 R15X8 Rear Tyre Size: 155 R12X8 (D) Front Left Side: Rear Left Side: DURATURN 6/6 mm Double King 9 mm Front Right Side: Double King 9 mm Rear Right Side: DURATURN 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	
Miscellaneous Items		0.00	0.00	0.00	
Labour		8,500.00	8,500.00	0.00	0.00
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	8,500.00	8,500.00	0.00	0.00
	- Excess (S\$)	0.00	1,600.00	-1,600.00	
	(S\$)	8,500.00	6,900.00	1,600.00	18.82
	+ GST 7.00/7.00% (S\$)	595.00	483.00	112.00	18.82
	Nett Amount (S\$)	9,095.00	7,383.00	1,712.00	18.82

**INSPECTION** 

Date of Assignment: 25/08/2022 Present Location: City Auto Pte Ltd (HQ)

CITY AUTO PTE LTD

BLK 8, SIN MING IND. ESTATE Date Inspected: 02/09/2022 Inspected At:

#01-60/62 SECTOR C SINGAPORE 575643.

Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG Manager: **CELINE FONG** 

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

12/30/22, 2:57 PM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: (Last Synchronised: 30 Dec 2022)

Parts: N/A TOYOTA DYNA 150 MANUAL 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBF4222U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

There are no new parts selected.

Report was unsubmitted during this print-out.

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	Refrigeration system (New) (Bent)	New	8,500.00	8,500.00
2	Supply and replace one (1) set Condenser Unit Assy (New sets)	New	-	-
3	Modify and rectify Condenser Unit Bracket	New	-	-
4	Supply and replace one (1) no Compressors	New	-	-
5	Supply and replace one (1) length belting	New	-	-
6	Supply and replace one (1) lot Piping	New	-	-
7	Supply and replace one (1) length Liquid Hose c/w fittings	New	-	-
8	Supply and replace one (1) length Suction Hose c/w fittings	New	-	-
9	Supply and replace one (1) length Discharge Hose c/w fittings	New	-	-
10	To test leakage by Nitrogen Gas (N2)	New	-	-
11	To tension and align belting works	New	-	-
12	To vacuum refrigeration system and replace R404gas	New	-	-
13	Testing and commissioning of Refrigeration System with Temperature and Pressure Test	New	-	-
14	Supply labour and services (1-year warranty)	New	-	-
	Gross Labour	8,500.00	8,500.00	
	Report was unsubmitted during this	orint-out.		

< END OF ESTIMATES >