

ASS. REC BY: Taufik

REF: CS/TM122008.194/Tq.43

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / IS / TP RES / OD RES / EVA / INV / MV  
To Inspect/vehicle No: \_\_\_\_\_  
at Works/tp m/s \_\_\_\_\_  
of \_\_\_\_\_  
Insured: \_\_\_\_\_  
Policy No. \_\_\_\_\_  
Claims No. \_\_\_\_\_  
Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
(Client's Record)  
Make of Veh: \_\_\_\_\_

Veh No: SMD 3897T Yr Regn: 2018 Dec  
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
Truck / Trailer or \_\_\_\_\_  
Make: Toyota Prius c.c. 1798  
Colour: Blue A/C: Insured / Std / NI / NA  
Sp. Reading: 381756 T/Radio: Insured / Std / NI / NA  
Eng/No: \_\_\_\_\_  
C/No: STDKR33FY203077725  
Gen. Cond: Good / Fair / Poor / Burnt  
Steering: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
Modi: (Nil) / S/Rim / STD A/Rim or \_\_\_\_\_  
Tyre Size: F: 195/65R15  
R: 195/65R15  
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or Winstlake  
Front Rear  
R/Bal. 6 mm R/Bal. 6 mm  
L/Bal. 6 mm L/Bal. 6 mm  
D.O.A. \_\_\_\_\_ D.O.I. 23/8/20  
Survey held at Carport Bayu  
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
O/S Rear  
The U/C / Chassis frame / Body Structure affected due to collision.

N/S	O/S

(Policy Condition)  
Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_  
IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
Est. Repairs: 2 days Res.: Yes or No  
Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
CA / REV / REP. / 24 HRS WP  
Date: \_\_\_\_\_ Person Contacted: Aray Vehicle: IN / OUT

Date / Time	Action / Instruction
	Taufikh confirmed lump sum: \$1050 and 2 days (red, 901.55 ,46%)

Date/Time, File Pass to?  : Preli. Report  
1) 28/10/22  : Final Report

Days Of Repair: 2  
Resurvey No. of Trip: 1

Date/Time, File Return to?  
2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
S + RS. \$:	
Photos	
Others	
TOTAL	

Rep. Format: \_\_\_\_\_  
Lump Sum / L.B.R. (P. 1050)

*Tokio*

*LKIC*

**REPAIR DETAILS**

**Reference**

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 25 Aug 2022)

**Parts:** 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** ComfortDelGro Engineering Pte Ltd/SHD3897T/25/08/2022 09:03

**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER COVER	25.00	0.00	<i>Ry</i> *503.04 FL
2	1		*REAR WHEEL RIM COVER RH	25.00	0.00	<i>inf</i> *177.70 FL
3	1		*REAR DOOR COMFORT APP RH	0	0.00	<i>inf</i> *80.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
<b>Sub Total (\$)</b>						<b>760.74</b>
<b>- List Item Discount on L Items (\$)</b>						<b>170.19</b>
<b>Total Parts (\$)</b>						<b>590.55</b>

ComfortDelGro Engineering Pte Ltd/SHD3897T/25/08/2022 09:03. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

### Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<b>Miscellaneous Items</b>			
1	1	OD/TP Case (Insurer)	11.00
<b>Sub Total (\$\$)</b>			<b>11.00</b>

### Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Labour Items</b>			
1	PANEL BEATING	New	350 550.00
2	SPRAY PAINTING	New	750 800.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,350.00</b>

ComfortDelGro Engineering Pte Ltd/SHD3897T/25/08/2022 09:03. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Handwritten notes:*  
 Tanjil 97495749  
 wp' 25/8/22 @ 4pm  
 c/b Resurvey after repair  
 Tanjil @ lkhants.com  
 2 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be surveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Customer: ARC Repair TP(CLSO)1

**JOB CARD** Sales Order: 4657408

JC No: 305527670

Customer Name: COMFORT TRANSPORTATION PTE LTD  
Customer No: 7010045  
Address: 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
Phone: (R) 65508755 (O)  
Fax: (P)  
Account Card No.


REGN NO: <b>SHD3897T</b>	MILEAGE
MAKE: <b>TOYOTA</b>	FUEL E.....1/2.....F
MODEL: <b>PRIUS HYBRID(G4)</b>	DATE/TIME IN <b>24.08.2022 15:40</b>
YR OF MANU: <b>13.12.2018</b>	TARGET DATE
CHASSIS CODE: <b>JTDKB3FU203077725</b>	COMPLETION DATE/TIME:

Accident Date: 23.08.2022  
Accident Nature: 3P 23.08.2022

JOB DESCRIPTION

/NO LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY: \_\_\_\_\_

\_\_\_\_\_  
SERVICE ADVISOR

\_\_\_\_\_  
CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.: **SHD3897T**  
Name: **CHIANG**

Vehicle No.: **SHD3897T**

Signature of Service Advisor \_\_\_\_\_ Signature/Date \_\_\_\_\_

Name of Service Advisor \_\_\_\_\_ Date \_\_\_\_\_

Returned to Service Reception upon collection

To be kept by Security Guard