

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Douglas Ong Chu Chong

Date: 21 Nov 2022

## **Preliminary Advice**

Insured Vehicle No	: FBP3207T		
TP Vehicle No	: SMY3493E	Accident Date	: 23/08/2022
Make	: HONDA SHUTTLE	Assignment Date	: 25/08/2022
Date of Inspection	: 31/08/2022	Est. Duration of Repair	: 2 DAYS
Inspection At	: JWG INTERNATIONAL PTE LTD (HQ) BLK 10, ANG MO KIO IND PARK 2A,, #03-08 AMK AUTOPOINT SINGAPORE 568047		

### **Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,642.40
Revised Amount	:S\$	1,238.04
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,238.04

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

### **Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( X ) Part-by-Part repair
- ( ) Lump Sum repair

- ( X ) The above survey was conducted on a 'without prejudice' basis.

Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.