



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                   |  |   |  |            |
|---|--|---|--|------------|
| MSIG INSURANCE (S) PTE LTD<br>4 SHENTON WAY #21-01<br>SGX CENTRE 2 SINGAPORE 068807 |  |   | Ref: CS/MSG22008196/AGcy3e2<br>Date: 01/11/2022<br>Code: MSG |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                   |  |   |  |            |
|   | Insured Veh.   | PUBLIC LIABILITY  | Veh. Inspected   | SME 9713L  |
|   | Policy No.   | 300391785   | Coverage (\$)  | 0.00       |
|   | Claim No.  |   | Excess (\$)  | 0.00       |
|   | Assign From  | CRYSTAL LEE   | Assign Date  | 25/08/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>                                       |  |   |  |            |
|   | Make & Model   | HONDA CIVIC   | c.c  | 1597       |
|   | Engine No.   | HIDDEN  | Year of Reg.   | 2018       |
|   | Chassis No.  | MRHFC5650JT001649   | Colour   | GREY       |
|   | Odometer   | 155728 KM   | Steering   | IN ORDER   |
|   | Brakes   | IN ORDER  | Modification   | SPORTS RIM |
|   | General  | GOOD  |  |            |
| <b>3. Conditions of Tyres</b>   |  |   |  |            |
|   |  | Size  | Make   | Balance    |
|   | R/H Front Tyre   | 215/50 R17  | MICHELIN   | 6 mm       |
|   | L/H Front Tyre   | 215/50 R17  | MICHELIN   | 6 mm       |
|   | R/H Rear Tyre  | 215/50 R17  | MICHELIN   | 6 mm       |
|   | L/H Rear Tyre  | 215/50 R17  | MICHELIN   | 6 mm       |
| <b>4. Description of Damages</b>  |  |   |  |            |
|   | THE VEHICLE SUSTAINED DAMAGES AT THE ROOFTOP.<br>DAMAGES SEE DETAILS.  |   |  |            |
| <b>5. General Information</b>   |  |   |  |            |
|   | Accident Date  | 22/08/2022  | Inspection Date  | 25/08/2022 |
|   | Survey held at   | KAI MOTOR TRADING<br>BLK 3007 UBI ROAD 1<br>#01-434<br>SINGAPORE 408701 |  |            |
| <b>5a. Remarks</b>  |  |   |  |            |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |  |            |
| <b>5b. Estimate Days of Repair</b>  |  |   |  |            |
|   | ESTIMATED NORMAL PERIOD FOR REPAIR:  |   | 8 Working Days   |            |