

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Oct 2022)

Parts: 143 MERCEDES-BENZ E200 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/SMF8907X/04/10/2022 11:10

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC REAR BUMPER	0.00	0.00	*860.00 F
2	1		*1 PC REAR BUMPER LOWER TRIM	0.00	0.00	*350.00 F
3	1		*1 PC REAR BUMPER LOWER BRACE BAR LH	0.00	0.00	*16.00 F
4	1		*1 PC REAR BUMPER LOWER BRACE BAR RH	0.00	0.00	*16.00 F
5	1		*1 PC REAR BUMPER REINFORCEMENT	0.00	0.00	*480.00 F
6	1		*2 PCS REAR PDC SENSORS @145/PC	0.00	0.00	*290.00 F
7	1		*1 PC REAR PDC SENSOR WIRE HARNESS	0.00	0.00	*115.00 F

F=Franchise part.

Total Parts (S\$)

2,127.00

Cheng Hoe Motor Pte Ltd/SMF8907X/04/10/2022 11:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO REPAIR BOOTLID,REAR END PANEL,REPLACE DAMAGED PARTS AND REALIGN THE SAME	New	500.00
2	PUTTY & RESPRAY REAR BUMPER,TRIM,BOOTLID,REAR END PANEL, reinforcement	New	600.00
3	RESET ECU / REPROGRAMME REVERSE SENSOR	New	50.00
Gross Labour Cost (S\$)			1,150.00

Cheng Hoe Motor Pte Ltd/SMF8907X/04/10/2022 11:10. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

1980
950
2930
49 #2300k

Not Notion
C/P #2300k
Return After Repair