



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: DAVID PHUA

Ref: CS/INC22008201/Rvy3e2

Date: 13/12/2022

Code: INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	PA 8705C	<b>Veh. Inspected</b>	PA 8539R
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	MT/1185514-002	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ANNIE KOH	<b>Assign Date</b>	25/08/2022

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA COASTER SUPER LWB	<b>c.c</b>	4009
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2009
<b>Chassis No.</b>	JTGEC538805000362	<b>Colour</b>	WHITE
<b>Odometer</b>	815770 KM	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	NIL
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
<b>R/H Front Tyre</b>	7.00 R16	GT RADIAL	7 mm
<b>L/H Front Tyre</b>	7.00 R16	GT RADIAL	7 mm
<b>R/H Rear Tyre</b>	7.00 R16 (D)	GT RADIAL	7/7 mm
<b>L/H Rear Tyre</b>	7.00 R16 (D)	GT RADIAL	7/7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

### 5. General Information

<b>Accident Date</b>	22/08/2022	<b>Inspect Date / Time</b>	25/08/2022 ( 04:08 PM )
<b>Survey held at</b>	POH LEE REPAIR & SERVICING OF VEHICLES NO.3 JOO KOON ROAD SINGAPORE 628967		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>	<b>8 Working Days</b>
--	-----------------------