## Veron Chen (LKKAuto)

From: Steven Tan <almightyautomotive@hotmail.com>

Sent: Thursday, 8 December 2022 11:17 AM

**To:** Veron Chen (LKKAuto); Rasul (LKKAuto); SUR; CS A Team

**Subject:** Re: PA8539R After repair photos

Hi Veron,

We are ok with the repair cost.

Regards Steven Tan

From: Veron Chen (LKKAuto) < veronchen@lkkauto.com>

Sent: Wednesday, December 7, 2022 12:08 PM

To: Rasul (LKKAuto) <Rasul@lkkauto.com>; SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>;

almightyautomotive@hotmail.com <almightyautomotive@hotmail.com>

Subject: RE: PA8539R After repair photos

Dear Steven,

As spoken, there is some calculation error.

We will be advising our principal a cost of repair L/S \$5,850 /- with 06 days of repair, subject to their approval.

Kindly Acknowledge.

Best Regards,

Veron Chen | Case Handler

**LKK Auto Consultants Pte Ltd** 

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Rasul (LKKAuto) < Rasul@lkkauto.com> Sent: Tuesday, 6 December 2022 5:00 PM

To: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>

Subject: FW: PA8539R After repair photos

From: Steven Tan <a href="mailto:sleen">almightyautomotive@hotmail.com</a>>

Sent: Tuesday, 6 December 2022 4:59:40 pm (UTC+08:00) Kuala Lumpur, Singapore

**To:** Rasul (LKKAuto) < <u>Rasul@lkkauto.com</u>> **Subject:** Re: PA8539R After repair photos

Hi Rasul,

We are ok with the amount,

Regards Steven Tan

From: Rasul (LKKAuto) < <a href="mailto:Rasul@lkkauto.com">Rasul@lkkauto.com</a>>
Sent: Tuesday, December 6, 2022 12:02 PM

**To:** Steven Tan < almightyautomotive@hotmail.com >

Subject: Re: PA8539R After repair photos

Hi Steven,

Audit checked part prices required to be audited.

We will be advising our principal a cost of repair L/S \$6,900.00 /- with 06 days of repair, subject to their approval.

Kindly Acknowledge.

Best Regards,

Rasul | Assessor

## LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Rasul@lkkauto.com</u> | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Rasul (LKKAuto) < Rasul@lkkauto.com > Sent: Wednesday, 2 November 2022 11:14 am

To: Steven Tan <a href="mailto:sleen">almightyautomotive@hotmail.com">almightyautomotive@hotmail.com</a>

Subject: Re: PA8539R After repair photos

Hi Steven,

noted will reply you asap

Best Regards,

Rasul | Assessor

**LKK Auto Consultants Pte Ltd** 

Phone: 6256-3561 | email: <u>Rasul@lkkauto.com</u> | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Steven Tan <almightyautomotive@hotmail.com>

**Sent:** Friday, 28 October 2022 8:50 am **To:** Rasul (LKKAuto) < Rasul@lkkauto.com > **Subject:** Re: PA8539R After repair photos

Hi Rasul,

Could we finalise on the PA8539R?

Regards Steven Tan

From: Steven Tan < almightyautomotive@hotmail.com >

Sent: Friday, October 7, 2022 2:43 PM
To: Rasul (LKKAuto) < Rasul@lkkauto.com > Subject: Re: PA8539R After repair photos

Hi Rasul,

As per attached.

Regards Steven Tan

From: Rasul (LKKAuto) < Rasul@lkkauto.com > Sent: Friday, October 7, 2022 2:39 PM

To: Steven Tan <almightyautomotive@hotmail.com>

Subject: Re: PA8539R After repair photos

i mean resurvey damage photos

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>Rasul@lkkauto.com</u> | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: Steven Tan <a href="mailto:sleen">almightyautomotive@hotmail.com</a>>

**Sent:** Friday, 7 October 2022 2:39 pm **To:** Rasul (LKKAuto) < Rasul@lkkauto.com > **Subject:** Fw: PA8539R After repair photos

From: Steven Tan

**Sent:** Monday, September 19, 2022 7:29 PM **To:** <a href="mailto:rasul@lkkauto.com">rasul@lkkauto.com</a>

Subject: PA8539R After repair photos

Hi Rasul,

As per attached is the add on quotation and the photos of after-repair.

Kindly let us know the finalisation amount. Thanks.

Regards Steven Tan 9668 9668