

POH LEE REPAIR & SERVICING OF VEHICLES

No. 3 Joo Koon Road (S628967)
Tel : 6862 9691 Fax : 68629693
ROC No.: 52799345W

Our Ref: TP/PA8539R/8149

23/8/2022

Poh Lee Bus Transport Pte Ltd
3 Joo Koon Road
Singapore 628967

QUOTATION

Dear Sir,

DOA : 22/8/22

Cost of Repair to Vehicle PA8539R

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear Bumper <i>buc /</i>	1	2,200.00	2,200.00 <i>1800</i>
2.	Rear Reinforcement Panel <i>7 X m</i>	1	1,250.00	1,250.00 <i>X</i>
3.	Rear Bumper Reverse Sensor <i>new /</i>	1	380.00	380.00 <i>220.50</i>
4.	Rear RHS Panel <i>64 / photo /</i>	1	1,700.00	1,700.00 <i>1450</i>
5.	Rear Windscreen Weatherstrip <i>new /</i>	2	112.45 <i>300.00</i>	224.90 <i>224.90</i>
6.	Rear Tail Lamp (LHS) <i>can /</i>	1	480.00	480.00 <i>449.50</i>
7.	Sealant <i>new /</i>	2	26.00	52.00 <i>50</i>
8.	Spray Painting on Rear affected portion with artwork	1	1,600.00	1,600.00 <i>750</i>
9.	Labour & Misc. Charges: To remove the affected parts & all relevant attachment & fittings to commence repairs; cut & weld the necessary parts as listed above; panel beat & reshapes the affected areas; replace the damaged components, reinstall & realign all necessary parts	1	2,400.00	2,400.00 <i>1000</i>
			SUB-TOTAL	S\$10,662.00 <i>1900</i>

~~5124.10~~ 3924.10
252
~~4293.67~~ 2943.07
S/N-272

Thanks you.
Yours faithfully,

Eddie Ong

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Rahul
HP 9001 0068
6 days
4S
25/08/22 01610
Ready after repair
email: rasul@lkkauto.com

POH LEE REPAIR & SERVICING OF VEHICLES

No. 3 Joo Koon Road (S628967)
Tel : 6862 9691 Fax : 68629693
ROC No.: 52799345W

Our Ref: TP/PA8539R/8149

23/8/2022

Poh Lee Bus Transport Pte Ltd
3 Joo Koon Road
Singapore 628967

QUOTATION (Add-On)

Dear Sir,

DOA :22/8/22

Cost of Repair to Vehicle PA8539R

With reference to the above-mentioned, we are pleased to quote as follows :-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Rear Emergency Door 61/	1	2,900.00	2,900.00
2.	Labour & Misc. Charges: To remove the affected parts & all relevant attachment & fittings to commence repairs; cut & weld the necessary parts as listed above; panel beat & reshapes the affected areas; replace the damaged components, reinstall & realign all necessary parts	1	400.00	400.00
			300	300
			SUB-TOTAL	S\$3,300.00

2500
252
1875
300

Thanks you.
Yours faithfully,

Eddie Ong

4293.07

272.00

1900.00

1875.00

300.00

8640.07

20%

6912.05

48-\$6,900/6 days

\$5850