

ASS. REC. BY:

REF:

INC / 22008202/Kn

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

05 days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ Will enal GIA over.

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee: _____

Transportation: _____

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

AUBURN AUTO PTE LTD
 UEN : 200805305G
 176 Sin Ming Drive Autocare #04-18, Singapore 575721
 Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Henrich
 96910663

NOT At home
 11 Sep @
 Morning After Pain
 5 days

Vehicle Number : SLK4761K

TOYOTA ALLION

Quantity	Description	Repairer's Estimate
	PART	
1	Boot <i>Rs</i>	\$1,200 ✓
1	boot lock <i>D.S</i>	\$800 ✓
1	rear bumper <i>Rs</i>	\$800 ✓
1	fender left <i>R</i>	\$600 X
1	fender right <i>R</i>	\$600 ✓
1	exhaust pipe <i>R</i>	\$350 X
4	reverse sensor x 2 <i>Rs</i>	\$650 <i>2000</i>
1	bumper bracket left <i>Rs</i>	\$350 X
1	bumper bracket right <i>R</i>	\$350 X
1	taillight left <i>Rs</i>	\$550 X
1	tail light right <i>Rs</i>	\$550 X
1	car plate	\$50 <i>7450</i>
1	car plate bracket <i>GMA</i>	\$50
1	spare tyre holder <i>R</i>	\$1,200 X
1	weatherstrip <i>GMA</i>	\$60 ✓
1	end panel garnish <i>ms D.S</i>	\$400 ✓
1	end panel metal <i>R</i>	\$400 ✓
1	reflector light left <i>GMA</i>	\$380 ✓
	<i>259</i>	
	LABOUR & MISC	
	Checking of wiring, lighting and resetting	\$300 <i>200</i>
	Remove and replace <i>family</i> damaged parts	\$350 <i>600</i>
	Apply undercoating on repaired and replaced panel	\$800 <i>600</i>
	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,200 <i>600</i>
	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident	\$1,000 <i>600</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: