

AUBURN AUTO PTE LTD

UEN : 200805305G

176 Sin Ming Drive Autocare #04-18, Singapore 575721

Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Keneth
96810663

NOT Authorized
11 Lm @ 3500h
Morning After Paint
5 days

Vehicle Number : SLK4761K

TOYOTA ALLION

Quantity	Description	Repairer's Estimate
	PART	
1	Boot <i>950.40 R</i>	\$1,200
1	boot lock <i>301.30 D.Y</i>	\$800
1	rear bumper <i>132</i>	\$800
1	fender left <i>R</i>	\$600
1	fender right <i>R</i>	\$600
1	exhaust pipe <i>R</i>	\$350
4	reverse sensor x 2 <i>D.Y</i>	\$650
1	bumper bracket left <i>R</i>	\$350
1	bumper bracket right <i>R</i>	\$350
1	taillight left <i>425 mgcm</i>	\$550
1	tail light right <i>425</i>	\$550
1	car plate	\$50
1	car plate bracket	\$50
1	spare tyre holder <i>R</i>	\$1,200
1	weatherstrip <i>60</i>	\$60
1	end panel garnish <i>358.00 mg D.Y</i>	\$400
1	end panel metal <i>R</i>	\$400
1	reflector light left <i>152 CM</i>	\$380
	<i>259</i>	
	LABOUR & MISC	
	Checking of wiring, lighting and resetting	\$300
	Remove and replace damaged parts <i>sanity</i>	\$350
	Apply undercoating on repaired and replaced panel	\$800
	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,200
	Respray including polishing and waxing on the changed body parts, repaired portions where consistent to the accident	\$1,000

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: