

ASS. REC. BY:

REF:

INC / 22008200/Kn

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Colour: _____

Sp. Reading: _____

Eng/No: _____

C/No: _____

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / R/Rim / STD A/Rim or

Tyre Size: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. _____

L/Bal. _____

D.O.A. _____

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/ Will email GIA over.

05/09/22 Kenneth informed lump sum: \$3500 and 5 days
(red. 9490, 73%)

Date/Time, File Pass to?

☐

: Prell. Report

1) 05/09/22

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$ 3500)

AUBURN AUTO PTE LTD
 UEN : 200805305G
 176 Sin Ming Drive Autocare #04-18, Singapore 575721
 Tel : 8797 8998 Email : auburnauto.insurance@gmail.com

Vehicle Number : SLK4761K

TOYOTA ALLION

*Keneth
96910663*

*Not Authorised
61 Day @
Resurvey After Paint
5 days*

Quantity	Description	Repairer's Estimate
	PART	
1	Boot <i>RM</i>	\$1,200 <i>✓</i>
1	boot lock <i>D/S</i>	\$800 <i>✓</i>
1	rear bumper <i>RM</i>	\$800 <i>✓</i>
1	fender left <i>RM</i>	\$600 <i>X</i>
1	fender right <i>RM</i>	\$600 <i>✓</i>
1	exhaust pipe <i>RM</i>	\$350 <i>X</i>
4	reverse sensor x 2 <i>RM</i>	\$650 <i>2000</i>
1	bumper bracket left <i>RM</i>	\$350 <i>X</i>
1	bumper bracket right <i>RM</i>	\$350 <i>X</i>
1	taillight left <i>RM</i>	\$550 <i>X</i>
1	tail light right <i>RM</i>	\$550 <i>X</i>
1	car plate	\$50 <i>745.00</i>
1	car plate bracket	\$50
1	spare tyre holder <i>RM</i>	\$1,200 <i>X</i>
1	weatherstrip <i>RM</i>	\$60 <i>✓</i>
1	end panel garnish <i>RM D/S</i>	\$400 <i>✓</i>
1	end panel metal <i>RM</i>	\$400 <i>✓</i>
1	reflector light left <i>RM</i>	\$380 <i>✓</i>
	<i>250</i>	
	LABOUR & MISC	
	Checking of wiring, lighting and resetting	\$300 <i>200</i>
	Remove and replace <i>family</i> damaged parts	\$350 <i>600</i>
	Apply undercoating on repaired and replaced panel	\$800 <i>600</i>
	Workmanship to dismantle above damaged parts, repairs including cut and weld, realign body structure	\$1,200 <i>600</i>
	Respray including polishing and waxing on the changed body parts, repaired portortions where consistent to the accident	\$1,000 <i>600</i>

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: