

ASS. REC. BY:

REF:

A16/ 22 008203/Ke

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 03 24 days

Res.: Yes or No

Lum Sum:

1. B. 1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S11B 9689Z

Yr Regn:

10, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Toy Pirus

C.C.

1798

Colour

M-P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

234844

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU 90 309 2349

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

175/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Pailun

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

C/S 157

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/8 @ 1827-03 Cahn

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS. \$

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech Invs (\$)

☐

: Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

Not Notified
Reserve B4 paint

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9689Z

81827-03

AAD2208-094

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 AUG 2022

SHB9689Z

JTDCB3FU903092349

TOYOTA

PRIUS **GEN 4**

18/08/2022

SMJ6855D/AIG

23/10/2020

PART	LIST
1 MIRROR ASSY, OUTER REAR VIEW, RH	\$ <i>su</i> 1,436.60 X
1 PANEL SUB-ASSY, FRONT DOOR, RH	\$ <i>n</i> 1,300.70 X
1 FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$ <i>su</i> 193.50 X
1 HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$ <i>su</i> 390.60 X
1 MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$ <i>su</i> 926.00 X
1 WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$ <i>su</i> 321.10 X
1 HINGE ASSY, FRONT DOOR, LOWER RH	\$ <i>n</i> 110.60 X
1 HINGE ASSY, FRONT DOOR, UPPER RH	\$ <i>n</i> 97.50 X
1 REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$ <i>su</i> 238.30 X
1 TAPE, BLACK OUT, NO.2 FRT RH	\$ <i>nn</i> 43.50 X
1 TAPE, BLACK OUT, NO.1 FRT RH	\$ <i>nn</i> 13.30 X
1 TAPE, BLACK OUT, NO.3 FRT RH	\$ <i>nn</i> 26.30 X
1 FENDER SUB-ASSY, FRONT RH	\$ <i>n</i> 977.80 X
1 EMBLEM, SIDE PANEL, RH	\$ <i>nn</i> 54.60 ✓
1 LINER, FRONT FENDER, LH	\$ <i>su</i> 210.30 X
1 COVER, FRONT BUMPER	\$ <i>bu</i> 521.00 ✓
1 MOULDING, FRONT BUMPER SIDE, RH	\$ <i>lt</i> 95.60 ✓
1 RIM	\$ <i>su</i> 1,900.10 X
1 HUB CAP	\$ <i>nn</i> 211.50 ✓
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$ <i>su</i> 594.80 X
TOTAL	\$ 9,663.70
25%	\$ 2,415.93
	\$ 7,247.78

Special Nett

1 FRT FENDER LINER CLIP	\$ <i>nn</i> 130.00 X
-------------------------	-----------------------

Trans-cab Auto Services Pte Ltd**AAD2208-094**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9689Z

1	FRT BUMPER CLIP	\$	<i>na</i>	65.00	✓
1	FRT BUMPER RETAINER CLIP	\$	<i>na</i>	75.00	X
1	DOOR STICKER TRANSCAB	\$	<i>na</i>	100.00	<i>60na</i>
1	DOOR TRIM CLIP	\$	<i>na</i>	75.00	X
1	DOOR WEATHERSTRIP CLIP	\$	<i>na</i>	80.00	X
TOTAL		\$		525.00	
TOTAL PARTS		\$		7,772.78	

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>na</i>	240.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		1,600.00	<i>300</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>na</i>	380.00	X
Putty And Spray Painting Of The Affected Portion.	\$		1,600.00	<i>660</i>
To reinstall rear bumper parking sensor.	\$	<i>na</i>	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i>	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	<i>20</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	<i>60</i>

Trans-cab Auto Services Pte Ltd

AAD2208-094

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9689Z

To remove and refit of rear fender fittings, attachment and
perform water seepage test.

	\$	<i>nn</i> 170.00 X
TOTAL	\$	5,100.00

Over All Total	\$	12,872.78
-----------------------	----	------------------

(PART-BY-PART) Repair Days~~20 Days~~*3 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: