

ASS. REC. BY:

REF:

A/G / 22008205/1K

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02

days

Res.: Yes or No

Lum Sum:

13.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 5282 J

Yr Regn:

11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

202297

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU 80 30 93119

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Wanli 195/65R15

R: 1798

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

20/5/22

D.O.I.

22/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

23/8

R1109.05 Car

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) :

Not Authored
Penny B4 pain

AAD2205-

81109.05

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5282J

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

22 AUG 2022

SHC5282J

JTDKB3FU803093119

200303878K

TOYOTA

PRIUS GEN 4

20/05/2022

SCP9998S/ AIG

30/11/2020

PART

- 1 COVER, FRONT BUMPER
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 COVER, FRONT BUMPER HOLE, LH
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 REINFORCEMENT SUB-ASSY, FRONT BUMPER
- 1 MOULDING, FRONT BUMPER SIDE, LH
- 1 BRACKET, FRONT BUMPER SIDE, LH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 FENDER SUB-ASSY, FRONT LH
- 1 FRONT FENDER EMBLEM LH
- 1 UNIT ASSY, HEADLAMP, LH

LIST

\$	Bu	521.00	✓
\$	su	110.50	X
\$	mi	30.20	✓
\$	su	80.20	X
\$	n	716.60	X
\$	cm	95.60	✓
\$	su	59.30	X
\$	su	422.50	X
\$	De	178.60	X
\$	n	977.80	X
\$	nn	54.60	X
\$	su	2,637.60	X

TOTAL \$ 5,884.50
25% \$ 2,828.00
\$ 8,484.00

Special Nett

- 1 FRT FENDER CLIP
- 1SET FRONT FENDER LINER CLIP
- 1SET FRONT BUMPER CLIP

\$	nn	65.00	X
\$	nn	75.00	X
\$	nn	90.00	X

TOTAL \$ 230.00

TOTAL PARTS \$ 9,530.50

LABOUR

Trans-cab Auto Services Pte Ltd**AAD2205-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5282J

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	1,600.00	200
	\$	nn 380.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn 240.00	X
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	220
To transfer of tire, rim and on wheel balancing.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	100

TOTAL \$ 4,380.00**Over All Total \$ 13,094.00****(PART-BY-PART) Repair Days**

20 days

2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: