

NOT Authorised

82701

AAD2206-129

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5886L**

Vehicle No.:  
Chassis No.:  
Co UEN:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration:

22 AUG 2022

**SHD5886L**

JTDKB3FU703079065

200303878K

TOYOTA

PRIUS

28/06/2022

**GBF7777R/ AIG.**

17/01/2019

PART	LIST	
1 COVER, REAR BUMPER	\$	442.60
1 REINFORCEMENT SUB-ASSY, REAR BUMPER	\$	332.70
1 COVER, REAR BUMPER, LOWER	\$	15.40
1 GUARD, REAR BUMPER, CENTER	\$	576.30
1 RETAINER, REAR BUMPER SIDE, LH	\$	116.50
1 RETAINER, REAR BUMPER SIDE, RH	\$	117.70
1 FILLER, REAR BUMPER EXTENSION, LH	\$	123.70
1 COVER, FLOOR UNDER, NO.1 LH	\$	175.10
1 COVER, FLOOR UNDER, NO.2 RH	\$	241.90
1 COVER, REAR FLOOR CTR	\$	229.90
1 COVER, DECK TRIM, REAR	\$	126.70
1 PANEL SUB-ASSY, BODY LOWER BACK	\$	650.30
1 LENS AND BODY, REAR LAMP, LH (LOWER)	\$	502.00
<b>TOTAL</b>	<b>\$</b>	<b>3,650.80</b>
<b>25%</b>	<b>\$</b>	<b>912.70</b>
	<b>\$</b>	<b>2,738.10</b>

**Special Nett**

1SET PARKING AID	\$	700.00	X
1SET REAR BUMPER CLIP	\$	95.00	X
1 REAR BUMPER PROTECTOR	\$	180.00	X
1SET REAR BUMPER RETAINER CLIP	\$	85.00	X
1SET TAILLAMP LOWER CLIP	\$	55.00	X
1 END PANEL TRIM CLIP	\$	65.00	X
<b>TOTAL</b>	<b>\$</b>	<b>1,180.00</b>	

**TOTAL PARTS \$ 3,918.10**

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5886L****AAD2206-129****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>na</i>	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i>	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	<i>501</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>na</i>	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	<i>na</i>	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	<i>na</i>	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	<i>na</i>	480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	X
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	<i>na</i>	250.00	X
Towing Fees	\$	<i>na</i>	150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	<i>2201</i>
To reinstall rear bumper parking sensor.	\$	<i>na</i>	170.00	X

**Trans-cab Auto Services Pte Ltd**

**AAD2206-129**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD5886L**

To Check Electrical Lighting Concerned.	\$	<i>nn</i> 170.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>4</i> 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	<i>4</i> 220.00	X
To conduct and perform a comprehensive vehicle diagnostic check and reset vehicle warning indicators.	\$	<i>7</i> 380.00	X
<b>TOTAL</b>	<b>\$</b>	<b>8,920.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>12,838.10</b>	

**(PART-BY-PART) Repair Days**

**25-DAYS**

*1 day*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: