

ASS. REC. BY:

REF:

C72/ 22 008212/ke

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

025 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHD 9322X

Yr Regn:

05, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M.P. White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

262702

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3F4803080032

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F: Wanli 195/65R15

R: Spilun

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

24/6/22

D.O.I.

22/8/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

29/8

1171.75 Cash

Date/Time, File Pass to?



: Prell. Report

1)

Date/Time, File Return to?



: Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Not Authoised
1/1/2022 8 11 H.75

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9322X

AAD2206-104

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 AUG 2022

SHD9322X

JTDKB3FU803080032

200303878K

TOYOTA

PRIUS

24/06/2022

XE3095X/CHINA

17/05/2019

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 FILLER, REAR BUMPER EXTENSION, LH
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 REAR TAILGATE TOYOTA LOGO
- 1 REAR TAILGATE WORDING 'PRIUS'
- 1 REAR TAILGATE WORDING 'HYBRID'

LIST

\$	442.60	X
\$	332.70	2
\$	15.40	X
\$	576.30	
\$	116.50	
\$	117.70	
\$	123.70	
\$	925.60	
\$	241.90	X
\$	229.90	
\$	126.70	
\$	650.30	
\$	47.90	
\$	54.60	
\$	54.60	

TOTAL \$ 4,056.40
25% \$ 1,014.10
\$ 3,042.30

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR BUMPER PROTECTOR
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP

\$	700.00	X
\$	95.00	6000
\$	150.00	
\$	200.00	
\$	130.00	
\$	80.00	
\$	80.00	
\$	180.00	
\$	85.00	
\$	65.00	

TOTAL \$ 1,765.00

TOTAL PARTS \$ 4,807.30

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9322X**AAD2206-104****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	na	300.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		2,200.00	2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	na	380.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	4	180.00	X
To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	4	480.00	X
To transfer of Fender fittings, attachments and perform water seepage test.	\$	4	480.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4	380.00	X
To check steering geometry and computer wheel alignment	\$	4	220.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	4	250.00	2201 X
Towing Fees	\$		150.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,200.00	2201
To reinstall rear bumper parking sensor.	\$	na	170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	101
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	4	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	4	220.00	X

Trans-cab Auto Services Pte Ltd**AAD2206-104**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD9322X

To conduct and perform a comprehensive vehicle diagnostic check and
reset vehicle warning indicators.

	\$	<i>nn</i> 380.00	X
TOTAL	\$	8,920.00	
Over All Total	\$	13,727.30	

(PART-BY-PART) Repair Days**25 DAYS***2 days*

- LKK Auto Consultants** hence notify
the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: