

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jacqueline Tan

Date: 12 Sep 2022

Preliminary Advice

Insured	: SMJ377G		
Vehicle No			
TP Vehicle		Accident Date	: 24/08/2022
No	: SHA8416G		
Make	: HYUNDAI AE IONIQ HEV	Assignment Date	: 26/08/2022
Date of	: 25/08/2022	Est. Duration of	: 3
Inspection		Repair	
Inspection At	: DING AUTOMOTIVE PTE LTD (SIN MING) BLK 10 #01-20 SIN MING, IND EST SEC C SINGAPORE 575645		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,743.20
Revised Amount	:S\$	2,036.64
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,036.64

Lump Sum Repair	:S\$	1,600.00
-----------------	------	----------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :