

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

24/08/2022 12:45

JOB-NO: 50114410

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

ADDRESS: 383 SIN MING DRIVE

64739522

SINGAPORE 575717 0

VEHICLE DETAILS

LICENSE NO: SHA8416G

TRANS: AUTO

CHASSIS: KMHC851CVKU164576

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 Di

ENGINE: G4LEKU296332

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,200.00	0.00	1,200.00		Y	200 ✓
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00		Y	X 111
3 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	240.00	0.00	240.00		Y	X 111
4 TO READJUST AND REALIGN HEADLAMP AIM	1.00	100.00	0.00	100.00		Y	30 ✓
5 TO CONDUCT TYRE BALANCING AND WHEEL ALIGNMENT	1.00	120.00	0.00	120.00		Y	X 111
6 TO VACUUM AND TOPUP A/C GAS FOR A/C CONDENSER	1.00	150.00	0.00	150.00		Y	X 111
7 TO REMOVE AND REFIT A/C CONDENSER, RADIATOR AND OTHER NECESSARY ITEM TO ENABLE BODYWORK REPAIR	1.00	220.00	0.00	220.00		Y	X 111
8 TO RESPRAY FRONT BUMPER	1.00	250.00	0.00	250.00		Y	200 ✓
9 TO RESPRAY FRONT BUMPER CENTER UPPER MOULDING	1.00	250.00	0.00	250.00		Y	100 ✓
10 TO RESPRAY FRONT BUMPER FOG LAMP COVER	1.00	250.00	0.00	250.00		Y	X 111
11 TO RESPRAY FRONT FENDER PANEL	1.00	250.00	0.00	250.00		Y	X 111
TOTAL:		3,200.00	0.00	3,200.00			

MATERIALS

1 FRONT BUMPER COVER	1.00	430.90	86.18	344.72	L	Y	
2 FRONT LH BUMPER RETAINER	1.00	28.00	5.60	22.40	L	Y	
3 FRONT LH BUMPER SIDE SUPPORT BRACKET	1.00	12.00	2.40	9.60	L	Y	
4 FRONT BUMPER ENERGY ABSORBER	1.00	86.90	17.38	69.52	L	Y	
5 FRONT BUMPER CENTER UPPER MOULDING	1.00	141.10	28.22	112.88	L	Y	
6 FRONT LH BUMPER FOG LAMP COVER	1.00	93.00	18.60	74.40	L	Y	
7 FRONT LH HEADLAMP	1.00	1,198.80	239.76	959.04	L	Y	
8 FRONT END MODULE CARRIER	1.00	949.30	189.86	759.44	L	Y	
9 FRONT LH FENDER PANEL	1.00	588.80	117.76	471.04	L	Y	
10 FRONT LH FENDER LINER	1.00	114.70	22.94	91.76	L	Y	
11 FRONT LH FENDER EMBLEM	1.00	26.80	5.32	21.28	L	Y	
12 FRONT LH WHEEL RIM COVER	1.00	346.40	69.28	277.12	L	Y	
13 FRONT BUMPER CLIP SET	1.00	55.00	0.00	55.00	S	Y	30 ✓
14 FRONT BUMPER RIVET SET	1.00	50.00	0.00	50.00	S	Y	30 ✓

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
15 FRONT BUMPER MOULDING CLIP <i>NE</i>	1.00	50.00	0.00	50.00	S	Y	<u>30</u>
16 FRONT FENDER LINER CLIP SET <i>X11</i>	1.00	55.00	0.00	55.00	S	Y	
17 RADIATOR COOLANT <i>X m</i>	1.00	120.00	0.00	120.00	S	Y	
TOTAL:		4,346.50	803.30	3,543.20			
TOTAL PARTS & LABOUR :		7,546.50	803.30	6,743.20			

EXCESS/LOADING:\$\$ 0.00

No. Of Day: 3 days

RE-SURVEY: BEFORE AFTER PAINTING

PART-BY-PART OR LUMP SUM: \$\$

DATE OF SURVEY: 25 / 08 / 22

SURVEYED BY: RASUL

CONTACT NO: 96016068

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

530.00

1416.64

90.00

2036.64

20%

1629.31

L/s - \$1,600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: