

(08/11/13) wef

ASS. REC. BY: Rom

REF:

CS3/SPF 22008221/Ry3

3948

Veron/Kusul 20/3/202
Parts Clarity
+ Price

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBT 9430Dat Workshop m/s ALBERT MOTORof 100% BUILT MERCEDES #01-12Insured: QX 580P SPF

Policy No. _____

Claims No. ACS/105/009/2022/053

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 15K

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: _____

days

Res.: Yes or No

Lum Sum: _____

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: _____

Veh No: FBT 9430DYr Regn: 2022 / July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: YAMAHA TISSc.c 155Colour: MULTI

A/C: Insured / Std / NI / NA

Sp. Reading: 947

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: RLCUG1610M4801658

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 90/80-17R: 120/70-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

IRC

Front

Rear

R/Bal. 4 mmR/Bal. 4 mm

L/Bal. _____ mm

L/Bal. _____ mm

D.O.A. 22/08/22D.O.I. 25/08/22

Survey held at

ALBERT MOTORDes. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT - 5KESTIMATE RANGE OF REPAIR / NO. OF DAYS - (4K-5K) / 4 days

29/3/23

Submit LS \$3450

repair range \$3450-\$3900

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 29/3/23-typist

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Days Of Repair: 5Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

) \$ + RS. \$ _____

) Photos

) Others

TOTAL

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 394B

Vehicle Details

Vehicle No.: FBT9430D

Vehicle to be Exported:

No

Intended Deregistration Date:

28 Aug 2022

Vehicle Make:

YAMAHA

Vehicle Model:

T155

Primary Colour:

Grey

Manufacturing Year:

2021

Engine No.:

G3R9E001657

Chassis No.:

RLCUG1610MY001658

Maximum Power Output:

\$2,371.00

Open Market Value:

04 Jul 2022

Original Registration Date:

04 Jul 2022

First Registration Date:

04 Jul 2022

Transfer Count:

1

Actual ARF Paid:

\$356.00

Intended PARF Rebate Details

PARF Eligibility:

No

PARF Eligibility Expiry Date:

No

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

03 Jul 2032

COE Category:

D - Motorcycle

COE Period (Years):

10

QP Paid:

\$10,000.00

COE Rebate Amount:

\$9,846.00

Total Rebate Amount:

\$9,846.00

The information contained herein is correct as at 28 Aug 2022

OK

Yamaha Sniper 155

Brand

Yamaha

Model

Yamaha Sniper 155

Engine Capacity

155cc

Class

2B

Type of Vehicle

Cubs

Condition

Brand New

SGD \$15977

Condition (CON)

(01)Bent (02)Dented (03)Distorted (04)Cracked (05)Cut (06)Scratched
(07)Deformed (08)Shifted (09)Buckled (10)Broken (11)Necessary
(12)Missing (13)Turn (14)Unconfirmed (15)Not Working

FOR MOTORCYCLE

ACTION (AC)

1. Replace (✓) 2. Repair (X) 3. Check (?)
4. Not Consistent (NC)

May 2005

Motorcycle

Vehicle No: **F8T 9430 D**

NAC	INC	Item	CON	AC	Qty
1003	991886	Front Number Plate			
3001	995065	Front Tyre			
3002	995095	Front Rim	No price	CUT	320
3003	994872	Front Tyre Rim Spoke			
3004	991771	Front Fender Wheel Guard	CUT		57
3005	991283	Front Brake Disc			
3006	991281	Front Brake Caliper			
3007	991785	Front Fork Assy	BT		500
3008	991787	Front Fork Inner Tube	bt		420
3009	991789	Front Fork Outer Tube	bt		255
3010	991167	Front Fork Bracket	bt		125
3011	991182	Front Fork Oil Seal	nec		10
3012	991174	Front Fork Garnish			
3013	992376	Front Headlamp Rim			
3014	992328	Front Headlamp			
3015	992337	Front Headlamp Bracket			
3016	992345	Front Headlamp Fairing	No	DT	195
3017	992130	Front Windshield			
3018	992134	Front Wing Mirror	RH	SCA	80
3019	995245	Front LH Signal Lamp	SCR		85
3020	995246	Front RH Signal Lamp	SCR		85
3021	992556	Meter Casing			
3022	992553	Meter Assy			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
3023	992446	Ignition Switch			
3024	992442	Ignition Key Assy			
3025	990706	Cowling Stay			
3026	994470	Steering Stem			
3027	994427	Steering Cone	SCR		150
3028	992299	Handle Bar			
3029	992312	Handle Bar Switch			
3030	992310	Handle Bar Grip			
3031	995184	Handle Bar Balancer LH			
3032	992300	Handle Bar Balancer RH	SCR		20
1252	992179	Fuel Tank			
3033	990438	Brake Reservoir			
3034	990621	Clutch Lever			
3035	992293	Hand Brake Lever			
3036	991119	Side Fairing	SCR		192
3037	994220	Side Fairing Top Garnish	No	DL	95
3038	994219	Side Fairing Inner Garnish			
3039	991118	Fairing Shield			
3040	992047	Front Top Fairing Inner Garnish			
3041	991123	Fairing Top Garnish			
3042	990538	Center Fairing			
3043	993378	Rear Fairing			
3044	991121	Fairing Stopper			
3045	991117	Fairing Lower			

NAC	INC	Item	CON	AC	Qty
1052	995074	Radiator			
1053	992738	Radiator Cowling			
3046	994146	Seat Assy			
3047	990915	Engine Crash Bar			
3048	990928	Engine Guard			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
3049	991144	Foot Brake			
3050	991154	Front Foot Rest			
3051	991779	Front Foot Rest Bracket			
3052	994269	Side Stand			
3053	992549	Main Stand			
3054	990615	Clutch Engine Cover			
3055	992478	Kick Starter Rubber			
3056	992477	Kick Starter Lever			
3057	991145	Foot Gear Shifter			
3058	993500	Rear Foot Rest			
3059	993501	Rear Foot Rest Bracket			
3060	992581	Exhaust Muffler Heat Shield	CUT		65
3061	991058	Exhaust Muffler Assy	DT		400
1403	993719	Rear LH Shock Absorber			
1445	993720	Rear RH Shock Absorber			
3062	995065	Rear Tyre			
3063	991200	Rear Rim			
3064	994872	Rear Tyre Rim Spoke			
3065	993474	Rear Fender Wheel Guard	SCR		75
3066	993443	Rear Fender Mudflap			
3067	992940	Rear Brake Disc			
3068	992936	Rear Brake Caliper			
3069	995236	Rear Spocket			
3070	990585	Chain			
3071	990580	Chain Guard			
3072	994530	Swing Arm			
1420	993819	Rear Sub frame			
3073	995245	Rear LH Signal Lamp	SCR		188
3074	995246	Rear RH Signal Lamp	SCR		88
3075	995251	Rear Taillamp			
1435	993626	Rear Number Plate			
3076	994192	Side Box			
3077	992927	Rear Box	SCR		200
3078	992928	Rear Box Bracket			
3079	991328	Emblem			
1436	990247	Sticker			
		DRIVER BASKET	CRA		45
		Rear Taillamp fairing	CRA		150

No of Items: _____ Assessor: _____

ORIGINAL COPY

Labour :**Veh. No.
FBT9439D**

- | | |
|--|-------|
| 1) Replacing accident damaged parts, check & repair accident affected areas. | \$600 |
| 2) Spray painting accident affected areas. | \$300 |
| 3) Check electrical wiring & lighting system for proper function. | \$30 |
| 4) Checking and repair fornt fork alignment according to specification. | \$60 |

Repair 5 day SUM\$990

320
57
500
420
255
125
10
196
80
85
85
150
20
192
95
65
400
75
88
88
200
45
150

SUM\$3701 SUM\$990

Total\$4691