



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS3/SPF22008221/Rvy3

ACCIDENT CLAIMS SECTION
(SPORE POLICE FORCE)
POLICE LOGISTICS BASE (PLB)

Date: 25/08/2022

1 HEMMANT ROAD SINGAPORE 438675

Code: SPF

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 580P	Veh. Inspected	FBT 9430D
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/053	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	25/08/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	22/08/2022	Inspection Date	25/08/2022
Survey held at	Blk 1006 Bukit Merah Rd #01-12		
Repairer	ALBERT MOTOR SUPPLY PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.