



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## DAMAGE ASSESSMENT REPORT

AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)

Ref: CS3/SPF22008221/Rvy3m4

ACCIDENT CLAIMS SECTION (SPORE POLICE  
FORCE) POLICE LOGISTICS BASE (PLB) 1  
HEMMANT ROAD SINGAPORE 438675

Date: 30/03/2023

ATTN: HAFIZUL FARHAN

Code: SPF

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	QX 580P	Veh. Inspected	FBT 9430D
Policy No.		Coverage (\$)	0.00
Claim No.	ACS/105/009/2022/053	Excess (\$)	0.00
Assign From	HAFIZUL FARHAN	Assign Date	25/08/2022

### 2. Vehicle Particulars & Condition

Make & Model	YAMAHA T155	c.c	155
Engine No.	HIDDEN	Year of Reg.	2022
Chassis No.	RLCUG1610MY001658	Colour	MULTI
Odometer	947 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80-17	IRC	4 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70-17	IRC	4 mm
L/H Rear Tyre			mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION, O/S AND N/S BODY.  DAMAGES SEE DETAILS.
---

### 5. General Information

Accident Date	22/08/2022	Inspect Date / Time	25/08/2022 ( 04:55 PM )
Survey held at	BLK 1006 BUKIT MERAH #01-12		
Repairer	ALBERT MOTOR SUPPLY PTE LTD		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------