

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrotauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SLR 4179E**

Made : Toyota

Model : Prius Hybrid 1.8S

Chassis No : _____

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Tailgate <i>BT</i>	1	\$ 1,126.60	\$ 1,126.60
2	Rear Tailgate Lock <i>X</i>	1	\$ 457.90	\$ 457.90
3	Rear Tailgate Cover Trim Board <i>X</i>	1	\$ 254.40	\$ 254.40
4	Rear Tailgate Trim Board, Centre <i>X</i>	1	\$ 159.60	\$ 159.60
5	Rear Tailgate Trim Board, Side RH <i>X</i>	1	\$ 92.50	\$ 92.50
6	Rear Tailgate Trim Board, Side LH <i>X</i>	1	\$ 92.50	\$ 92.50
7	Rear Tailgate Trim Board Rear <i>X</i>	1	\$ 360.80	\$ 360.80
8	Rear Tailgate Weatherstrip <i>TN</i>	1	\$ 365.20	\$ 365.20
9	Rear Tailgate Outer Garnish <i>X</i>	1	\$ 896.30	\$ 896.30
10	Rear Tailgate Emblem <i>ACC</i>	1	\$ 52.90	\$ 52.90
11	Rear Tailgate "Prius" Emblem <i>ACC</i>	1	\$ 60.80	\$ 60.80
12	Rear Tailgate "Hybrid Synergy Drive" Emblem <i>ACC</i>	1	\$ 52.40	\$ 52.40
13	Rear Tailgate Lock Striker <i>X</i>	1	\$ 98.70	\$ 98.70
14	Rear Windscreen Glass c/w Moulding <i>ACC</i>	1	\$ 1,778.30	\$ 1,778.30
15	Rear Windscreen Glass c/w Moulding Lower <i>ACC</i>	1	\$ 1,569.70	\$ 1,569.70
16	Rear Tailgate Spoiler <i>X</i>	1	\$ 953.70	\$ 953.70
17	Rear Bumper <i>RE</i>	1	\$ 499.90	\$ 499.90
18	Rear Bumper Lower Cover <i>RE</i>	1	\$ 552.60	\$ 552.60
19	Rear Bumper Under Side Cover RH <i>X</i>	1	\$ 232.00	\$ 232.00
20	Rear Bumper Under Side Cover LH <i>X</i>	1	\$ 232.00	\$ 232.00
21	Rear Bumper Under Side Cover Centre <i>X</i>	1	\$ 552.60	\$ 552.60
22	Rear Bumper Towing Cover <i>AT</i>	1	\$ 82.70	\$ 82.70
23	Rear Bumper Side Retainer RH <i>X</i>	1	\$ 94.80	\$ 94.80
24	Rear Bumper Side Retainer LH <i>X</i>	1	\$ 94.80	\$ 94.80
25	Rear Bumper Arm RH <i>X</i>	1	\$ 139.60	\$ 139.60
26	Rear Bumper Arm LH <i>X</i>	1	\$ 139.60	\$ 139.60
27	Rear Bumper Reinforcement <i>BT</i>	1	\$ 318.80	\$ 318.80
28	Rear Bumper Side Seal RH <i>X</i>	1	\$ 148.40	\$ 148.40
29	Rear Bumper Side Seal LH <i>X</i>	1	\$ 148.40	\$ 148.40
30	Rear Wiring Assembly <i>X</i>	1	\$ 582.40	\$ 582.40
31	Rear Taillamp Assembly Upper RH <i>X</i>	1	\$ 557.90	\$ 557.90
32	Rear Taillamp Assembly Upper LH <i>X</i>	1	\$ 557.90	\$ 557.90

33	Rear Taillamp Assembly Lower RH	X	1	\$	548.40	\$	548.40
34	Rear Taillamp Assembly Lower LH	X	1	\$	548.40	\$	548.40
35	Rear Taillamp Quarter Panel RH	X	1	\$	216.00	\$	216.00
36	Rear Taillamp Quarter Panel LH	X	1	\$	216.00	\$	216.00
37	Rear End Panel	X	1	\$	602.10	\$	602.10
38	Rear End Panel Top Garnish	X	1	\$	165.80	\$	165.80
39	Rear Spare Tyre Panel	X	1	\$	667.70	\$	667.70
40	Rear Spare Tyre Panel Top Board	X	1	\$	101.40	\$	101.40
41	Rear Sponge Tool Box Centre	X	1	\$	186.20	\$	186.20
42	Rear Sponge Tool Box Trim RH	X	1	\$	398.00	\$	398.00
43	Rear Sponge Tool Box Trim LH	X	1	\$	398.00	\$	398.00
44	Rear Spare Tyre Panel Side RH	X	1	\$	287.30	\$	287.30
45	Rear Spare Tyre Panel Side LH	X	1	\$	287.30	\$	287.30
46	Rear Fender RH	X	1	\$	836.70	\$	836.70
47	Rear Fender LH	X	1	\$	836.70	\$	836.70
48	Rear Fender Inner Trim RH	X	1	\$	387.70	\$	387.70
49	Rear Fender Inner Trim LH	X	1	\$	387.70	\$	387.70
50	Rear Fender Inner Cowling RH	X	1	\$	174.20	\$	174.20
51	Rear Fender Inner Cowling LH	X	1	\$	174.20	\$	174.20
52	SMART Transmitter Key	X	1	\$	447.10	\$	447.10
53	Rear Exhaust Pipe	X	1	\$	1,163.40	\$	1,163.40
54	Rear Exhaust Mounting	X	1	\$	40.70	\$	40.70
55	Rear Exhaust Insulator	X	1	\$	314.60	\$	314.60
Parts Sub Total :						\$	22,692.30
25% Discount						\$	5,673.08
PARTS TOTAL :						\$	17,019.23

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	1	\$ 50.00	\$ 50.00
2	Rear Bumper Clips - Set	1	\$ 50.00	\$ 50.00
3	Rear Taillamp Clips - Set	1	\$ 50.00	\$ 50.00
4	Rear Fender Inner Trim Clips - Set	1	\$ 50.00	\$ 50.00
5	Rear End Panel Top Garnish Clips - Set	1	\$ 50.00	\$ 50.00
6	Rear Fender Inner Cowling Clips - Set	1	\$ 40.00	\$ 40.00
7	Rear Tailgate Inner Trim Board Clips - Set	1	\$ 60.00	\$ 60.00
8	Rear Tailgate Sealant	1	\$ 150.00	\$ 150.00
9	Rear Taillamp Quarter Panel Sealant	1	\$ 120.00	\$ 120.00
10	Rear End Panel Sealant	1	\$ 150.00	\$ 150.00
11	Rear Spare Tyre Panel Sealant	1	\$ 150.00	\$ 150.00
12	Rear Fender RH Sealant	1	\$ 150.00	\$ 150.00
13	Rear Fender LH Sealant	1	\$ 150.00	\$ 150.00
14	Rear Windscreen Glass Upper Sealant	1	\$ 150.00	\$ 150.00
15	Rear Tailgate Glass Lower Sealant	1	\$ 150.00	\$ 150.00
16	Rear Bumper Reverse Sensor - Set	1	\$ 250.00	\$ 250.00
17	Rear Tailgate Reverse Camera - Set	1	\$ 550.00	\$ 550.00

SPECIAL NETT TOTAL : \$ 2,320.00

Nos.	LABOUR	\$
1	To Panel Beat, Remove & Refix Parts	\$ 2,400.00
2	To Spray Paint Affected Areas	\$ 1,800.00
3	Wiring & Bulb Check	\$ 100.00
4	To Remove & Refix Rear Windscreen Glass Upper	\$ 150.00
5	To Remove & Refix Rear Windscreen Glass Lower	\$ 150.00
6	To Transfer Rear Tailgate Mechanism	\$ 150.00
7	To Remove & Refix Rear Tailgate Reverse Camera	\$ 150.00
8	To Remove & Refix Rear Bumper Reverse Sensor	\$ 120.00
9	To Remove & Refix Rear Exhaust Pipe to facilitate repairs	\$ 150.00
10	To apply anti rust on affected parts	\$ 150.00
11	To Remove & Refix Interior Upholstry to facilitate repairs	\$ 150.00
12	To Remove & Refix Fuel Tank to facilitate repairs	\$ 200.00
13	To Conduct Water Leak Test	\$ 100.00
14	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$ 480.00
LABOUR TOTAL :		\$ 6,250.00

600
600
30
120
60
60
40
40
X
60
60
X
X
X

PARTS TOTAL : \$ 17,019.23
SPECIAL NETT TOTAL : \$ 2,320.00
LABOUR TOTAL : \$ 6,250.00
GRAND TOTAL : \$ 25,589.23

5 Days.

L/S

After repair photos.

Case Q23

8288 0282

26/8/22

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair work commencing
- To disassemble and repair the vehicle
- Parts and materials to be replaced
- Third party claims to be settled
- No further work to be done
- Supply of materials to be replaced
- Is subject to a 10% discount on the total bill

Acknowledged by Repairer:

Signature:

Date: