



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0737/2022/EQ
DATE : 25-Aug-22
WIP : 39090

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/8/2022.

YOUR INSURED VEH NO : SNF 3211 R

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR. XIE XINHONG
ADDRESS : BLK 687D CHOA CHU KANG DR
#08-372
SINGAPORE 684687
TELEPHONE : HP +65 92395588
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 5116955700-02
VEHICLE NO : **SMT 1233 D**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI
MODEL YEAR : 27/3/2020
ENGINE NO : CHZ C35697
CHASSIS NO : WAUZZZ8V8LA006450
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Aug-22
PLACE OF ACCIDENT : JURONG GATEWAY TOWARDS
TOH GUAN ROAD



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMT 1233 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID.	S/N \$ 360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 900.00	
3	TO RESPRAY REAR BUMPER.	\$ 900.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 2,352.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMT 1233 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 2,317.00	
2	REAR BUMPER GUIDE SECTION - LH / RH	2	\$ 36.00	
3	REAR BUMPER SPOILER	1	\$ 264.00	
4	REAR BUMPER LOCKING MECHANISM	2	\$ 67.00	
5	REAR BUMPER REFLECTOR - LH / RH	2	\$ 92.00	
6	REAR BUMPER REINFORCEMENT BEAM	1	\$ 642.00	
7	REAR BUMPER BRACKET - LH / RH	2	\$ 63.00	
8	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	
9	REAR PARKING AID SEAL RING	4	\$ 10.00	
10	SUNDRIES		\$ 350.00	
TOTAL SPARE PARTS		:	\$ 4,372.00	
TOTAL LABOUR CHARGES		:	\$ 2,352.00	
GRAND TOTAL		:	\$ 6,724.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT