

Vehicle Damage Assessment Report for [GBC2323R]

Estimate Created: 10/05/2023 15:14 by Insurlogic 4 (Insurlogic_Pte_Ltd)

Owned: 10/05/2023 15:27 by Insurlogic 4 (Insurlogic_Pte_Ltd)

General Information

Insurance Company	ERGO	Claim Number
Claim Type	TP	
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number

Vehicle Information

Brand	Toyota	Model	Estima
Engine Type			
License Plate Number	GBC2323R	VIN (or Chassis #)	

Vehicle Condition

Damaged Diagram	Odometer	0.00 Km
	Tyres Condition	
	Front Left	mm
	Front Right	mm
	Rear Left	mm
	Rear Right	mm

Comments

- VEHICLE MAKE AND MODEL: TOYOTA DYNA	Insurlogic 4 (10/05/2023 15:26)
- FINAL REVIEW BASE ON INFORMATION PROVIDED BY LKK: CONCLUDED THE COST OF REPAIR AT \$3,200.00 WITH 5 WORKING DAYS	Insurlogic 4 (10/05/2023 15:26)

Parts

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear tailgate		1	1137.00	-25.00 %	852.75
Tailgate hinges		4	15.00	-25.00 %	45.00
Rear tailgate lower panel		1	455.20	-25.00 %	341.40
Rear tail lamp		2	270.00	-25.00 %	405.00
Rear taillamp panel		2	110.00	-25.00 %	165.00
Exhaust		1	530.00	-25.00 %	397.50
Rear exhaust pipe mounting		1	24.00	-25.00 %	18.00
Rear spare wheel bracket		1	245.00	-25.00 %	183.75

Parts Subtotal 2,408.40

Materials

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Tailgate 70KM/H sticker		1.0	15.00	0.00 %	15.00
Tailgate 13 Pax sticker		1.0	15.00	0.00 %	15.00
Rear tailgate step		1.0	250.00	0.00 %	250.00
Rivets		10.0	1.00	0.00 %	10.00
Rear number plate bracket		1.0	120.00	0.00 %	120.00
Rear number plate garnish		1.0	20.00	0.00 %	20.00
Rear number plate		1.0	35.00	0.00 %	35.00

Materials Subtotal 465.00

Labor**Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	600.00	0.00 %	600.00
To remove and replace rear tailgate aluminium cover	RnR	40.00	0.00 %	40.00
To remove and refit exhaust	RnR	80.00	0.00 %	80.00
To checking wiring	RnR	30.00	0.00 %	30.00
To reseal anti rust	RnR	50.00	0.00 %	50.00

Paint

Description	Paint Type	Cost	Markup/Disc %	Price
-------------	------------	------	---------------	-------

Spray painting	Full spray	400.00	0.00 %	400.00
Labor Rate	S\$ 50 / Hour	General Labor Subtotal		800.00
		Paint Labor Subtotal		400.00
		Labor Subtotal		1,200.00

Summary

Repair Cost	4,073.40
Discount(20 %)	(814.68)
	3,258.72
Excess	(0.00)
GST(0.00 %)	0.00
Grand Subtotal	3,258.72