

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Estimate" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance

Ryder Auto Pte Ltd

2 Kaki Bukit Ave 2 #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryder@workshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

Vehicle: GBC2323R

Model: TOYOTA DYNA
2/11/2009

Accident Date: 24/8/2022

Location: PIE (AIRPORT) BEFORE STEVEN ROAD EXIT

3P: GBJ7073S (ERGO)

JTFA13SY201C2009S2

7P Ergo-
Celine.

S/Nos	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear tail gate <i>Dented</i>	1584.57	1137.	
2	1 pc	Rear tail gate '70 km/h' sticker <i>3 new</i>		20.00	15
3	1 pc	Rear tail gate '13 pax' sticker		20.00	15
4	2 pcs	Rear tail gate o/s & n/s lock <i>2 new</i>	80.00	X	
5	1 pc	Rear tail gate o/s & n/s lock handle <i>3 new</i>	97.80	X	
6	4 pcs	Rear tail gate hinges <i>Bent</i>	60.00	X	
7	4 pcs	Rear tail gate hinges pins <i>new</i>	20.00	X	
8	1 pc	Rear tail gate lower panel <i>Dented</i>	455.20	X	
9	2 pcs	Rear tail gate o/s & n/s rubber stopper <i>2 new</i>	40.00	X	
10	2 pcs	Rear tail gate o/s & n/s rubber stopper bracket <i>3 new</i>	90.00	X	
11	1 pc	Rear tail gate step <i>Bent</i>		500.00	250.
12	2 pcs	Rear o/s & n/s railing <i>Not new</i>			
13	2 pcs	Rear o/s & n/s tail lamp <i>Cracked</i>	540.00	X	
14	2 pcs	Rear o/s & n/s tail lamp panel <i>Bent</i>	220.00	X	
15	1 pc	Rear end panel <i>Repeated</i>	510.40	X	
16	1 pc	Rear aluminium cover <i>Not new</i>		400.00	X
17	1 pc	Rear floor aluminium <i>Not new</i>		800.00	X
18	10 pcs	Rivets <i>New</i>		10.00	X
19	1 pc	Exhaust <i>Bent</i>	765.00	530	
20	4 pcs	Rear exhaust pipe mounting <i>Damaged</i>	24.00	X	
21	1 pc	Rear reg. no. plate bracket <i>Bent</i>		120.00	X
22	1 pc	Rear regn no. plate garnish <i>Bent</i>		20.00	X
23	1 pc	Rear regn no. plate <i>Missing</i>		35.00	X
24	1 pc	Rear spare wheel bracket <i>Damaged</i>	798.80	245	
25	1 pc	Rear spare tyre rim (big) <i>2 new</i>	600.00	X	
26	1 pc	Rear spare tyre (big)		200.00	X
27	1 pc	Rear spare tyre rim (small)	500.00	X	
28	1 pc	Rear spare tyre (small)		150.00	X
Sub Total:			6,385.77	2,275.00	0.00
			25%	0%	0%
After Less %:			4,789.33	2,275.00	0.00
Labour					
1		To dismantle rear portion, straighten, cutting & welding.	1,200.00	600.	
2		To spray painting.	600.00	400.	
3		To remove and replace rear canopy	80.00	X	
4		To remove & replace rear tail gate aluminium cover	100.00	40.	
5		To remove & refit exhaust	120.00	80	
6		To check wiring.	80.00	30	
7		To re seal anti rust.	80.00	50.	
Sub Total:				2,260.00	
Total:				9,324.33	
After Less 20%:				7,459.46	

3211.20

2408.40

S.N: 465

1200

Adrian C
w/s 25/08/22.
05 Days.
total: 4073.40
w/s: 3.21C ✓

Chan San Choon
Director
DipEng, AAE MIMI, MSAE(Aust)



bizSAFE 8778 1999
24 hr accident call

Mobil 1



GBC2323R ESTIMATEP1

PAYNOW