LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ERGO Insurance Pte. Ltd. 8 Temasek Boulevard #04-01 Suntec Tower Three Singapore 038988 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 11 May 2023

Preliminary Advice

Insured Vehicle No : GBJ7073S

TP Vehicle No : GBC2323R Accident Date : 24/08/2022

Make : TOYOTA DYNA 150 MANUAL 3SEATER Assignment Date : 25/08/2022

Date of Inspection : 25/08/2022 Est. Duration of Repair : 05

Inspection At : RYDER AUTO PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	9,324.33
Revised Amount	:S\$	4,073.40
Check Items (Estimated)	:S\$	
Total	:S\$	4,073.40
Lump Sum Repair	:S\$	3,200.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.	
		Kindly let us have your authorisation.	

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments : The above survey was conducted on a "Without Prejudice" basis.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.