



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: OH VALE			Ref: CS/ASM22008232/Gcy3m4 Date: 28/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJR 9719M	Veh. Inspected	SMW 4233T
	Policy No.	GA521663	Coverage (\$)	0.00
	Claim No.	S2M049N6	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	25/08/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLB200	c.c	1332
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	W1N2476872W029092	Colour	GREY
	Odometer	31373 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/50 R19	PIRELLI	6 mm
	L/H Front Tyre	235/50 R19	PIRELLI	6 mm
	R/H Rear Tyre	235/50 R19	PIRELLI	6 mm
	L/H Rear Tyre	235/50 R19	PIRELLI	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/08/2022	Inspection Date	29/08/2022
	Survey held at	XIN YUN AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-59 AUTOBAY @ KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	