

REC BY: T. G. J. M.

REF:

CS3/CT/27008234/Tgys

ASSIGNMENT

From: _____ Date: _____

Estimated cost _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 4155K

IDAC Accident Report _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SL92195D Yr Regn: 20/9/89

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz C200 C.C. 1497

Colour: Grey A/C: Insured / Std / Nil / NA

Sp. Reading: 48893 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WDD 2050772R 48105

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRim / STD A/Rim or

Tyre Size: F: 225/50R17

R: ~ ~

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / DHTSU / PIR / SUMI /

TOYO / YOKO, or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.L.

25/8/22 0340pm

Chip Soon

Rear o/s

Date / Time Action / Instruction

Repair Range: 47500 - 48500, 9 days

Date/Time, File Pass to?

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Insp (\$

Survey Fee: _____

Transportation: _____

B + RS \$1

Phone: _____

Other: _____

Formet: _____

Line 8/11/13/15