

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT22002463	<b>Page</b>	1
<b>Registration No</b>	: SLB2556Y	<b>Date</b>	: 25. Aug 2022		
<b>Chassis No</b>	: JHMRC1890GC202229	<b>Customer No.</b>	: WZC008		
<b>Model</b>	: ODYSSEY 2.4 EXV-S 16YM	<b>Svc Advisor</b>	: NG SIN HAI		
<b>Owner's Name</b>	: ESO THOMAS KARIANMANAYIL	<b>Engine No</b>	: K24W72010905		
<b>Ins Policy No.</b>	:	<b>Date   Time</b>	: 25. Aug 2022 10:38:33 AM		
<b>Date of Accident</b>	: 25/8/2022	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER: OWNER INSURER: ACC DATE: SURVEYED BY: DATE: REF NO: TP INSURER: TP VEH:						
RS-TMP3040L	VPC 4PCS REAR SENSORS	1	320.00		320.00	22.40	342.40
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N)	1	45.00		45.00	3.15	48.15
04814-T6A-M00ZA	TONGUE SET,R.FR.SEATBELT OUTER	1	477.30	25	357.97	25.06	383.03
04818-T6A-M00ZA	TONGUE SET,L.FR.SEATBELT OUTER	1	477.30	25	357.97	25.06	383.03
67010-T6A-000ZZ	PANEL COMPR.FR.DOOR	1	958.30	25	718.72	50.31	769.03
77100-T6A-000ZA	PANEL COMPINSTRUMENT UPPER	1	941.80	25	706.35	49.44	755.79
77820-T6A-N80	MODULE ASSYPASSENGER	1	2785.60	25	2089.20	146.24	2235.44
74890-T6A-J01	GARNISH ASSYRR.LICENSE	1	246.70	25	185.02	12.95	197.97
68100-T6A-Q10ZZ	TAILGATE COMP	1	1146.20	25	859.65	60.18	919.83
74440-T6A-003	WEATHERSTRIPTAILGATE	1	125.70	25	94.27	6.60	100.87
74891-T6A-003	MOLDING ASSYRR.LICENSE GARN	1	187.90	25	140.92	9.86	150.78
74900-T6A-003ZB	GARNISH ASSYTAILGATE SPOILER	1	677.40	25	508.05	35.56	543.61
91513-T6A-003	CLIPTAILGATE SPOILER	6	2.60	25	11.70	0.82	12.52
75701-T6A-000	EMBLEMH	1	28.20	25	21.15	1.48	22.63
04715-T6A-900ZZ	FACERR.BUMPER	1	608.30	25	456.22	31.94	488.16
33505-SLJ-013	REFLECTOR ASSYR.RR.	1	48.50	25	36.37	2.55	38.92
33555-SLJ-013	REFLECTOR ASSYL.RR.	1	48.50	25	36.37	2.55	38.92
71502-T6A-003ZB	FACER.RR.BUMPER GARNISH	1	84.70	25	63.52	4.45	67.97
71507-T6A-003ZB	FACE,L.RR.BUMPER GARNISH	1	84.70	25	63.52	4.45	67.97

Printed on 25/8/2022 11:08:55 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT22002463	<b>Page</b>	2
<b>Registration No</b>	: SLB2556Y	<b>Date</b>	: 25. Aug 2022	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: JHMRC1890GC202229	<b>Svc Advisor</b>	: NG SIN HAI	<b>Engine No</b>	: K24W72010905
<b>Model</b>	: ODYSSEY 2.4 EXV-S 16YM	<b>Date   Time</b>	: 25. Aug 2022 10:38:33 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: ESO THOMAS KARIANMANAYIL	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 25/8/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
71512-T6A-921ZB	SPOILER ASSY,R.RR.SIDE	1	125.80	25	94.35	6.60	100.95
71517-T6A-921ZB	SPOILER ASSY,L.RR.SIDE	1	125.80	25	94.35	6.60	100.95
71593-T6A-003	SPACERR.RR.BUMPER SIDE	1	20.40	25	15.30	1.07	16.37
71598-T6A-003	SPACERL.RR.BUMPER SIDE	1	20.40	25	15.30	1.07	16.37
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
66100-T6A-300ZZ	PANEL COMP,RR.	1	493.20	25	369.90	25.89	395.79
04656-T6A-300ZZ	PAN SET3RD SEAT	1	372.60	25	279.45	19.56	299.01
72841-SH3-315	OILSHEET	3	43.50	25	97.87	6.85	104.72
84431-T6A-J01ZA	LINING ASSYTAILGATE LOWER	1	220.80	25	165.60	11.59	177.19
84441-T6A-J01ZA	POCKETTAILGATE LINING PULL	1	11.50	25	8.62	0.60	9.22
84615-T6A-N71ZD	LINING COMPR.RR.SIDE	1	809.20	25	606.90	42.48	649.38
84640-T6A-003ZA	LINING ASSYRR.PANEL	1	110.90	25	83.17	5.82	88.99
84643-T6A-Q01ZA	COMP LIDTOOL	1	65.70	25	49.27	3.45	52.72
84665-T6A-N71ZD	LINING COMPL.RR.SIDE	1	841.90	25	631.42	44.20	675.62
73214-T6A-003	MOLDINGRR.WINDSHIELD SIDE	2	19.20	25	28.80	2.02	30.82
73215-T6A-003	MOLDINGR.RR.WINDSHIELD CORNER	1	18.10	25	13.57	0.95	14.52
73216-T6A-003	MOLDINGL.RR.WINDSHIELD CORNER	1	18.10	25	13.57	0.95	14.52
73221-SR4-000	SPACERRR.W/SHIELD	4	4.20	25	12.60	0.88	13.48
73225-TM8-000	RUBBER AWINDSHIELD DAM	1	3.90	25	2.92	0.20	3.12
73226-SZW-000	DAMPERSTD 5X5	2	9.10	25	13.65	0.96	14.61
76711-T6A-003	CAPPIVOT	1	5.20	25	3.90	0.27	4.17
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	2	60.00		120.00	8.40	128.40
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N)	1	45.00		45.00	3.15	48.15
33100-T6A-Q11	HEADLIGHT ASSYR.WITH LED	1	2516.00	25	1887.00	132.09	2019.09
33150-T6A-Q11	HEADLIGHT ASSY,L.WITH LED	1	2516.00	25	1887.00	132.09	2019.09
33900-TY0-003	LIGHT ASSY, R. FR.FOG	1	285.90	25	214.42	15.01	229.43
33905-T6A-003	BRACKETR.FR.FOGLIGHT	1	67.70	25	50.77	3.55	54.32
33950-TY0-003	LIGHT ASSY, L. FR.FOG	1	285.90	25	214.42	15.01	229.43
33955-T6A-003	BRACKETL.FR.FOGLIGHT	1	67.70	25	50.77	3.55	54.32

Printed on 25/8/2022 11:08:55 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT22002463	<b>Page</b>	3
<b>Registration No</b>	: SLB2556Y	<b>Date</b>	: 25. Aug 2022	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: JHMRC1890GC202229	<b>Svc Advisor</b>	: NG SIN HAI	<b>Engine No</b>	: K24W72010905
<b>Model</b>	: ODYSSEY 2.4 EXV-S 16YM	<b>Date   Time</b>	: 25. Aug 2022 10:38:33 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: ESO THOMAS KARIANMANAYIL	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 25/8/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
71104-T6A-J81ZA	GARNISHR.FR.BUMPER	1	49.80	25	37.35	2.61	39.96
71109-T6A-J81ZA	GARNISHL.FR.BUMPER	1	49.80	25	37.35	2.61	39.96
60100-T6A-000ZZ	HOOD COMP	1	718.70	25	539.02	37.73	576.75
60120-T6A-000ZZ	HINGE COMPR.HOOD	1	50.80	25	38.10	2.67	40.77
60170-T6A-000ZZ	HINGE COMPL.HOOD	1	50.80	25	38.10	2.67	40.77
74120-T6A-003	LOCK ASSYHOOD	1	113.70	25	85.27	5.97	91.24
74141-T6A-010	INSULATORHOOD	1	101.00	25	75.75	5.30	81.05
74145-T6A-000	STAY,HOOD OPEN	1	10.90	25	8.17	0.57	8.74
74154-T6A-000	SEHOOD GARNISH ASSY	1	93.90	25	70.42	4.93	75.35
90672-SNB-003	HOLDERROD	1	2.10	25	1.57	0.11	1.68
80050-SP0-000	LABEL AIR CONDITIONER CAUTION	1	1.90	25	1.42	0.10	1.52
19043-PLA-E00	LABELCOOLANT INFORMATION	1	5.80	25	4.35	0.30	4.65
77875-SDA-G80	LABEL SRS CAUTION	1	0.80	25	0.60	0.04	0.64
71121-T6A-003	BASEFR.GRILLE	1	180.80	25	135.60	9.49	145.09
71122-T6A-J01	MOLDINGFR.GRILLE	1	338.20	25	253.65	17.76	271.41
75700-TA0-A00	EMBLEMFR.	1	30.80	25	23.10	1.62	24.72
90301-ST0-003	NUT,PUSH 3MM	2	2.10	25	3.15	0.22	3.37
04711-T6A-900ZZ	FACE,FR.BUMPER	1	749.30	25	561.97	39.34	601.31
71105-T6A-901	GRILLEFR.BUMPER LOWER	1	71.90	25	53.92	3.77	57.69
71108-T6A-P00	LOWER PLATEFR.BUMPER	1	157.40	25	118.05	8.26	126.31
71110-T6A-000	AIR SPOILERFR.BUMPER	1	99.00	25	74.25	5.20	79.45
71112-T6A-921ZE	SPOILER ASSYR.FR.SIDE	1	104.10	25	78.07	5.46	83.53
71117-T6A-921ZE	SPOILER ASSY,L.FR.SIDE	1	104.10	25	78.07	5.46	83.53
71130-T6A-310ZZ	BEAM COMP,FR.BUMPER	1	312.40	25	234.30	16.40	250.70
71140-T6A-003	BEAMR.FR.BUMPER UPPER	1	37.30	25	27.97	1.96	29.93
71151-T6A-911	BASE,MID GRILLE	1	205.60	25	154.20	10.79	164.99
71152-T6A-J81ZA	UPPER MOLDING,MIDDLE GRILLE	1	166.00	25	124.50	8.72	133.22
71153-T6A-J81ZA	MOLDING,MIDDLE GRILLE	1	158.90	25	119.17	8.34	127.51
71190-T6A-003	BEAML.FR.BUMPER UPPER	1	37.30	25	27.97	1.96	29.93

Printed on 25/8/2022 11:08:55 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT22002463	<b>Page</b>	4
<b>Registration No</b>	: SLB2556Y	<b>Date</b>	: 25. Aug 2022	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: JHMRC1890GC202229	<b>Svc Advisor</b>	: NG SIN HAI	<b>Engine No</b>	: K24W72010905
<b>Model</b>	: ODYSSEY 2.4 EXV-S 16YM	<b>Date   Time</b>	: 25. Aug 2022 10:38:33 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: ESO THOMAS KARIANMANAYIL	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 25/8/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
71193-T6A-003	SPACERR.FR.BUMPER SIDE	1	12.60	25	9.45	0.66	10.11
71198-T6A-003	SPACERL.FR.BUMPER SIDE	1	12.60	25	9.45	0.66	10.11
91505-TM8-003	CLIP,BUMPER	14	2.30	25	24.15	1.69	25.84
60210-T6A-300ZZ	FENDER COMPR.FR.	1	587.20	25	440.40	30.83	471.23
60260-T6A-300ZZ	FENDER COMPL.FR.	1	587.20	25	440.40	30.83	471.23
74100-T6A-000	FENDER ASSYR.FR.INNER	1	129.20	25	96.90	6.78	103.68
74105-T6A-000	ENCLOSURER.FR.FENDER	1	28.20	25	21.15	1.48	22.63
74150-T6A-000	FENDER ASSYL.FR.INNER	1	129.20	25	96.90	6.78	103.68
74155-T6A-000	ENCLOSUREL.FR.FENDER	1	28.20	25	21.15	1.48	22.63
74201-T6A-000	GARNISHR.FR.FENDER	1	35.50	25	26.62	1.86	28.48
74206-T6A-000	GARNISHL.FR.FENDER	1	35.50	25	26.62	1.86	28.48
90682-SEA-003	CLIP ABUMPER	4	2.60	25	7.80	0.55	8.35
91505-TM8-003	CLIP,BUMPER	14	2.30	25	24.15	1.69	25.84
80111-T6A-003	CONDENSER COMP	1	729.90	25	547.42	38.32	585.74
08CLA-P9911LK8	COOLANT ANTI-FREEZE TYPE 2	6	23.20	25	104.40	7.31	111.71
19010-5X6-J02	RADIATOR COMP	1	1442.10	25	1081.57	75.71	1157.28
60400-T6A-310ZZ	BULKHEAD COMPFR.	1	493.20	25	369.90	25.89	395.79
19015-5X6-J01	SHROUD COMP	1	116.00	25	87.00	6.09	93.09
19020-5A4-H02	FAN COMPCOOLING	1	59.40	25	44.55	3.12	47.67
19030-5X6-J01	MOTOR,COOLING FAN	1	319.40	25	239.55	16.77	256.32
Sum Item					20878.87	1,461.47	22,340.34
BOSUN	SUNDRIES	1	110.00		110.00	7.70	117.70
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	250.00		250.00	17.50	267.50
BOJSE	SEALANT FOR REAR END PANEL	1	120.00		120.00	8.40	128.40
BOJSE	SEALANT FOR REAR FLOOR PANEL	1	120.00		120.00	8.40	128.40
BOJSE	SEALANT FOR TAILGATE	1	120.00		120.00	8.40	128.40
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00		250.00	17.50	267.50

Printed on 25/8/2022 11:08:55 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT22002463	<b>Page</b>	5
<b>Registration No</b>	: SLB2556Y	<b>Date</b>	: 25. Aug 2022	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: JHMRC1890GC202229	<b>Svc Advisor</b>	: NG SIN HAI	<b>Engine No</b>	: K24W72010905
<b>Model</b>	: ODYSSEY 2.4 EXV-S 16YM	<b>Date   Time</b>	: 25. Aug 2022 10:38:33 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: ESO THOMAS KARIANMANAYIL	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 25/8/2022				

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
BM102D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	650.00		650.00	45.50	695.50
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	650.00		650.00	45.50	695.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	650.00		650.00	45.50	695.50
BODAMKIT	WINDSCREEN DAM KIT.	1	120.00		120.00	8.40	128.40
BKRP02M	CUT OFF & RENEW RR PANEL.	1	5000.00		5000.00	350.00	5350.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00		4000.00	280.00	4280.00
BKBU01R	REMOVE, RE-FIX AND ALIGN REAR VIEW CAMERA	1	650.00		650.00	45.50	695.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	250.00		250.00	17.50	267.50
BMC01D	REMOVE & INSTALL RADIATOR WITH FITTINGS.	1	480.00		480.00	33.60	513.60
BMA01D	REMOVE & INSTALL A/C CONDENSER WITH FITTINGS.	1	530.00		530.00	37.10	567.10
BKBH11B	CUT OFF & RENEW BULKHEAD FR L HOUSING COMP.	1	6000.00		6000.00	420.00	6420.00
BP06R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (6P)	1	4000.00		4000.00	280.00	4280.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	650.00		650.00	45.50	695.50
BKDR12K	STRAIGHTEN ALIGN FR R DOOR INCLUDING FITTINGS ON	1	1200.00		1200.00	84.00	1284.00
BME00D	REMOVE & INSTALL ENGINE ASSY GEARBOX & OTHERS	1	1800.00		1800.00	126.00	1926.00
BMI00D	REMOVE & INSTALL DASHBOARD INSTRUMENTAL PANEL	1	1800.00		1800.00	126.00	1926.00
BML12R	REMOVE & RENEW ENGINE WIRE HARNESS. RESET ECU	1	1800.00		1800.00	126.00	1926.00
BMS00R	RENEW BOTH DRIVER & PASSENGER AIRBAG ASSY ECU &	1	1500.00		1500.00	105.00	1605.00
BMS02R	REMOVE & RENEW SEATBELT TENSIONER, ECU & CRASH SEN	1	1500.00		1500.00	105.00	1605.00
BO-TOW	TOWING SERVICES (MBBS)	1	250.00		250.00	17.50	267.50
Sum Labor					<b>34450.00</b>	<b>2,411.50</b>	<b>36,861.50</b>

Survey By

Printed on 25/8/2022 11:08:55 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT22002463	<b>Page</b>	6
<b>Registration No</b>	: SLB2556Y	<b>Date</b>	: 25. Aug 2022		
<b>Chassis No</b>	: JHMRC1890GC202229	<b>Customer No.</b>	: WZC008		
<b>Model</b>	: ODYSSEY 2.4 EXV-S 16YM	<b>Svc Advisor</b>	: NG SIN HAI		
<b>Owner's Name</b>	: ESO THOMAS KARIANMANAYIL	<b>Engine No</b>	: K24W72010905		
<b>Ins Policy No.</b>	:	<b>Date   Time</b>	: 25. Aug 2022 10:38:33 AM		
<b>Date of Accident</b>	: 25/8/2022	<b>Surveyor Name</b>	:		
		<b>Survey Date</b>	:		
		<b>Authorisation Date</b>	:		

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
Date & Time					<b>Total Amount</b>	55,328.87	3,872.97
Excess							59,201.84
Status					<b>Total (Inclusive of GST)</b>		<b>59,201.84</b>
Signature							

**Printed on 25/8/2022 11:08:55 AM**

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	25/08/2022 11:30 (SGT)
Reported by	Both
Date of Accident	25/08/2022 07:10 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	PIE TOWARDS TUAS
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLB2556Y
-----------------------------	----------

#### INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	ESO THOMAS KARIANMANAYIL
NRIC No	SXXXX083G
Email Address	ESOTHOMAS@YAHOO.COM
Mobile Phone No	(Phone) +65-98620561
Alternative Phone No	-

#### VEHICLE PARTICULARS

Manufacturer	Honda
Model	Odyssey
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2400

#### INSURANCE COMPANY

Name of Insurance Company	Liberty Insurance Pte Ltd
Policy Number / Cover Note Number	-

#### DRIVER

Name of Driver	ESO THOMAS KARIANMANAYIL
NRIC No	SXXXX083G
Date Of Birth	17/01/1971
Occupation	Indoor

Date Of Driving Pass	13/10/2003
Driving experience	18 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-98620561
Alt. Phone Number	-
Email Address	ESOTHOMAS@YAHOO.COM
Address	S
Address complement	-
Postcode	-
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	4
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJT6050S
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-

Address  
 Address complement  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 Details of property damaged in accident  
 No. Of Passenger (Including Driver)

PASSENGER 1

Name  
 Gender

#### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGK969P  
 Vehicle Manufacturer  
 Vehicle Model  
 Vehicle Variant  
 Vehicle Colour  
 Vehicle Category Private car  
 Name of Driver  
 Contact Number  
 Address  
 Address complement  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 Details of property damaged in accident  
 No. Of Passenger (Including Driver)


#### DETAILS OF OTHER VEHICLE PROPERTY 3


Vehicle Registration Number SLZ7281E  
 Vehicle Manufacturer  
 Vehicle Model  
 Vehicle Variant  
 Vehicle Colour  
 Vehicle Category Private car  
 Name of Driver  
 Contact Number  
 Address  
 Address complement  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 Details of property damaged in accident  
 No. Of Passenger (Including Driver)


# SKETCH PLAN

## IMPORTANT NOTICE


1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")  
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

  
Policyholder's Signature / Date & Time

  
Driver's Signature (If driver is not the policyholder) / Date & Time

  
Witnessed by Reporting Centre Personnel

## Sketch Plan




**Describe Circumstances of the Accident**


I was driving on PIE to Clementi Avenue 6,  
 the front vehicle C jam brake and I start to  
 jam brake too. And the collision happened.  
 When I get down of my vehicle A, I realised  
 it was a 4 car chain collision.

**Declaration**

We declare the foregoing particulars are true in every respect.

  
 Policyholder's Signature / Date &  
 Time

Driver's Signature (if driver is not the policyholder) / Date  
 & Time

  
 Witnessed by Reporting Centre  
 Personnel

