

SLA4085G. 2016 Feb.

TPAXA.

Nissan Teana. 2488 CC

Xiao Tony.

MNTRCAL33Z0003632

Rear Number Plate	Bent	30(SW).	✓
Rear Number Plate Holder	del'd	30(SW)	✓
Rear Number Plate Lamp	x 02. ^{mt} m	$48.2 \times 2 = 96.40.$	✗
Rear Bumper	Distorted	899.40	✓
Rear Bumper Clips.	m	30(SW)	✓
Rear Bumper Side Holder	x 02 ^{2nd}	$48.2 \times 2 = 96.40$	✓
Rear Bumper Reinforcement.	Bent	360.30.	✓
Rear Bumper Reinforcement Stay	^{Bent} x 02	$91.7 \times 2 = 183.40.$	✓
Rear Bumper Sponge	crush'd	133.80	✓
Rear Bumper Undercover	del'd	175.10	✓
Rear Bumper Undercover Clips.	m	20(SW)	✓
Reverse Sensor	x 04. ^{2nd}	$225 \times 4 = 900.$	✓
Rear End Panel	Distorted	467.20.	✓
Rear End Panel Top Garnish.	del'd	180.80	✓
Rear End Panel Top Garnish Clips.	del'd	20(SW)	✓
Rear End Panel Sealant.	m	60(SW)	✓
Rear End Panel Antenna Sensor	crush'd	189.50	✓

SLA4085G.

Taillap x 02	Culd	$470.6 \times 2 = 941.20$ ✓
Taillap lower Bracket x 02		258.40
Taillap Panel x 02	Lt Buckled	$258.4 \times 2 = 516.80$
Bootlid	pistoned	1080.80 ✓
Bootlid Lock	2nd	184.20 ✓
Bootlid Weatherstrips	lt	194.40 ✓
Bootlid Hinge x 02	Bent	$75.9 \times 2 = 151.80$ ✓
Bootlid Outer Chrome Moulding.	Culd	351.10 ✓
Bootlid Inner Trim Cover	2nd	179.60 ✓
Bootlid Inner Trim Cover Clips.	lt	30(SN) ✓
Reer Camen.	Dangd.	480(SN) 380(SN)
Reer Fender x 02	Lt Buckled	$1268.7 \times 2 = 2537.40$ ✓
Reer Fender Inner Trim Cover x 02	tern	$285.2 \times 2 = 570.40$ ✓
Reer Fender Inner Trim Cover Clips.	ra	60(SN) ✓
Reer Fender Inner Shield x 02	2nd	$78.9 \times 2 = 157.80$ ✓
Reer Fender Inner Shield clips.	lt	40(SN) ✓
Reer Fender Glass clw Moulding x 02	AT new	$633.3 \times 2 = 1266.60$ ✓ 633.30

SLA 40856.

Rear Windscreen Moulding	3 per	189.40. ✓
Rear Windscreen Sealant.		60(SN). ✓
Spare Tyre Panel	Buckled	1298.10 ✓
Spare Tyre Panel Sealant	2 per	60(SN) ✓
Spare Tyre Insulation Pad.		280(SN) 200(SN) ✓
Spare Tyre Panel Top Board.	2 hnd	305.60 ✓
Spare Tyre Panel Upholstery Tray.	1st m	350(SN) X.
Spare Tyre Panel Side Sponge x 02.	1st m	249.1 x 2 = 498.20 ✓
Spare Tyre Lock Screw.	1st m	39.40. X
Rear Exhaust Pipe x 02	Bent	723.4 x 2 = 1446.80 ✓
Rear Exhaust Pipe Mount x 02	1st m	354 x 2 = 70.80 X
Rear Exhaust Pipe Gasket x 02.	1st m	38.2 x 2 = 76.40 ✓
Centre Exhaust Pipe.	1st m	994.10. X
Nissan Logo	2	62.40. ✓
Teana Wording	1st m	66.40. ✓
2.5 XV Wording.		62.70 ✓
X-Tronic Emblem.		68.20. ✓

SLA40856.

Front Number Plate	} Missing	30(SN) ✓
Front Number Plate Holder		30(SN) ✓
Front Number Plate Garish. Del'd		65.50 ✓
Front Bumper Del'd		866.10 ✓
Front Bumper Clips M		30(SN) ✓
Front Bumper Side Holder x 02	M	$45.2 \times 2 = 90.40$ ✓
Front Bumper Reinforcement Dented		585.30 ✓
Front Bumper Reinforcement Cover	could	158.90 ✓
Front Bumper Reinforcement Stay x 02	Dented	$95 \times 2 = 190$ ✓
Front Bumper Lower Beam. Best		188.40 ✓
Front Bumper Undercover Del'd		298.90 ✓
Front Bumper Undercover Clips. New		30(SN) ✓
Front Bumper Fog Lamp x 02	} M M	$288.1 \times 2 = 576.20$ ✓
Front Bumper Fog Lamp Cover x 02		$89.4 \times 2 = 178.80$ ✓
Front Bumper Day Running Light x 02		$366.1 \times 2 = 732.20$ ✓
Front Bumper Nozzle Pump x 02	LH Dented	233.90 $233.9 \times 2 = 467.80$ ✓
Front Bumper Sensor x 02	Dented	$215 \times 2 = 430$ ✓
Front Bumper Sensor Holder x 02	M	$25 \times 2 = 50$ ✓

SLA4085G.

Front Grille	crack	659.60. ✓
Front Grille clips.	2 per	30(SN) ✓
Front Grille Logo.		68.90. ✓
Headcup x 02	crack	1610.9 x 2 = 3221.80. ✓ =
Headcup lower Bracket x 02		
Bonnet	Dented	1028.80. ✓
Bonnet Lock	dry	65.40. ✓
Bonnet Hinge x 02	Best	72.1 x 2 = 144.20. ✓
Bonnet Weatherstripe	new	89.40. X
Bonnet Insulator	crumpled	245.40. ✓
Bonnet Insulator Clips.	new	30(SN) ✓
Bonnet Damper x 02	new	241.1 x 2 = 482.20. X
Front Fender x 02	Buckled	701.9 x 2 = 1403.80. ✓
Front Fender Inner Shield x 02	2 per	131.7 x 2 = 263.40. X
Front Fender Inner Shield Clips	new	60(SN) X
Front Support Panel	Repair	753.40 X
Front Support Panel Top Garnish.	def	198.40. ✓

SLA4085G.

Horn x 02 NE per

$69.1 \times 2 = 138.20$ ✓

Oil Cooler. Dented

451.10. ✓

Air Con Condenser Dented

1250.60. ✓

Air Con Condenser Side Guide x 02 Behind

$35.1 \times 2 = 70.20$ ✓

Radiator Dented

849.40. ✓

Radiator Cowling Cracked

249.40. ✓

Fan Blade x 02 Ignition

$135 \times 2 = 270$ ✓

Fan Motor x 02

$350.6 \times 2 = 701.20$ ✓

Radiator Spare Tank. NE per

85.60 ✓

Radiator Coolant. New

50 (SN). ✓

Wiper Washer Tank. NE per

109.40. ✓

Sleeping Air Bag.

Sleeping Air Bag Sensor

Activated

1694.20 ✓

$204 \times 2 = 408$ ✓

2210.40. ✓

Passenger Air Bag.

Passenger Air Bag Sensor

$254.2 \times 2 = 508.40$ ✓

1850.40. ✓

Dashboard

Torn

$740.4 \times 2 = 1480.80$ ✓

Seat Belt x 02

Activated

798.40. ✓

Air Bag Control Unit.

Air Duct. Cracked

151.40. ✓

36493.90

32844.51

S.N: 1090

SLA 4085G

Panel Beating (Front)	1400 800
Spray Painting (Front)	1400 1000.
Wiring (Front).	100 30
To spray buff coat (Front)	150 50
To remove condenser and to top up air con gas	120 60
To remove radiator and to top up coolant	120 60
To remove driver and passenger air bags.	450 350
To remove dashboard	350 220.
To remove seat belts.	300 120
To reset air bag settings.	480 300
To remove front bumper sensors.	100 50.
	3040

SLA 4085G.

Panel Beating (Rear)	2000	1600
Spray Painting (Rear)	1800	1400
Wiring (Rear)	120	30
To remove reverse sensor.	120	50
To remove rear camera.	120	50
To spray full coat (Rear)	250	120
To remove upholstery and rear seat	350	200
To transfer bootlid fittings.	150	60
To remove rear windscreen.	180	120
To remove rear exhaust pipes	300	120
To remove centre exhaust pipe.	700	X
To remove rear door hinges	200	60
Towing Fees	80 ✓	3870
Total: 40844.51		
2/s: 28K (Nett Value)		
28 Days		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

28K
24 days