

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT					
	LONPAC INSURAN	NCE BHD		Ref:	CS3/LPC22005489/Kvy3m4
	300 BEACH ROAD #17-04/07 THE CO	NCOURSESINGAPORE 199555		Date:	15/06/2022
				Code:	LPC2
1.	Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	GBH 8076M	Veh. Inspected		SDH 3338S
	Policy No.		Coverage (\$)		0.00
	Claim No.	22/22/22/VC05/025909	Excess (\$)		0.00
	Assign From	GERALD POH	Assign Date		09/06/2022
2.	2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES C200 (A)	c.c		1497
	Engine No.	HIDDEN	Year of Reg.		2020
	Chassis No.	WDD2050772R509148	Colour		METALLIC DARK BLUE
	Odometer	36699 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3.	Conditions of Tyres				
		Size	Make		Balance
	R/H Front Tyre	225/45 R18	BRIDGESTONE		7 mm
	L/H Front Tyre	225/45 R18	BRIDGESTONE		7 mm
	R/H Rear Tyre	225/45 R18	BRIDGESTONE		7 mm
	L/H Rear Tyre	225/45 R18	BRIDGESTONE		7 mm
4. Description of Damages					
	THE VEHICLE SUS	STAINED DAMAGES AT THE FRONT O/S DOOR.			
5.	General Information				
	Accident Date	07/06/2022	Inspect Date / T	ime	13/06/2022 (12:27 PM)
	Survey held at	HIAP LEK AUTOMOBILE TRADING			
		160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722			
5a.	Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

Report Ref No. CS3/LPC22005489/Kvy3m4

Inspected By

KONG SENG CHEONG

Licensed Appraiser

The

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser