

OH APPRAISAL SERVICESBLK 34, #02-309, TOA PAYOH, LORONG 5
SINGAPORE (310034)

Mobile : 97982959 Fax : 63975857 email : oh3434@yahoo.com.sg

VEHICLE DAMAGE INSPECTION REPORTMr. Koh Choon Meng Darren
Bik 26 Cuscaden Road
#13-04
Singapore 249722Our Ref : SDH3338S/TP5042
Date : 08 August 2022**REFERENCES**

Claim Type	: Third Party	Date of Accident	: 07 June 2022
Vehicle No.	: SDH3338S	Date of Assignment	: 13 June 2022
June	: Mercedes Benz	Date of Inspection	: 13 June 2022
Model	: C 200	Date of Re-inspn.	: 14 June 2022
Reg. Date	: 12 March 2020	Chassis No	: WDD2050772R509148
Color	: Blue	Engine No	: Blocked
Odometer	: 73502 km		

TYRE CONDITION

	<u>Front near side</u>	<u>Front off side</u>	<u>Rear near side</u>	<u>Rear off side</u>
Make	Bridgestone	Bridgestone	Bridgestone	Bridgestone
Size	220 R18	220 R18	220 R18	220 R18
Thread Balance	5 mm	5 mm	6 mm	6 mm

GENERAL DESCRIPTION OF DAMAGE (PHOTOGRAPHS ATTACHED)

The vehicle sustained damage at Front and Rh side portion

INSPECTION AND ADJUSTMENTOriginal Quotation : \$10,428.00 Revised Assessment \$7,300.00 Lump sum

In accordance to your instruction, we have not authorized repairs.

In normal circumstances, repairs to the vehicle would take approximately
(5) days to complete. (Survey at Hiap Lek Automobile Trading.)

This survey was conducted on a "WITHOUT PREJUDICE" basis.

S/N	Description	Qty	Condition	Original Quotation	Revised Quotation	
<u>Material</u>						
1	Front fender Rh	1	Bent	990.00	990.00	X
2	Front door Rh	1	Dented	1,809.00	1,809.00	
3	Front door inner sponge Rh@\$65/-	3	Grazed	195.00	195.00	
4	Front door wing mirror Rh	1	Cracked	1,148.00	1,148.00	
5	Front door wing mirror signal Rh	1	Grazed	169.00	169.00	
6	Front door wing mirror w/signal outer cover Rh	1	Cracked	226.00	226.00	
7	Front door outer handle Rh	1	Grazed	579.00	579.00	X
8	Front door outer handle end Rh	1	Grazed	86.00	86.00	X
9	Front door regulator gear & motor assy Rh	1	Faulty	618.00	618.00	
10	Front door inner trim board	1	Grazed	1,800.00	1,800.00	X
11	Front door weatherstrip Rh	1	Necessary	207.00	207.00	
12	Front door top hinge Rh	1	Bent	135.00	135.00	X
13	Front door bottom hinge Rh	1	Bent	151.00	151.00	X
14	Rocker panel chrome moulding Rh	1	Grazed	125.00	125.00	
				8,238.00	8,238.00	
0 % and 10% discount				0.00	823.80	
				8,238.00	7,414.20	
<u>Special nett items</u>						
15	Front door inner trim board clip	1 set		40.00	40.00	Nec
Parts total				8,278.00	7,454.20	
<u>Labour & Misc.</u>						
1)	Labour charge to remove-refit, panel beat, straighten, re-align and repair of Front Rh fender, front Rh door, front Rh door wing mirror and others relevant accident damages.			1,000.00	800.00	300
2)	To check wirings and lightings			50.00	30.00	
3)	To supplied and applied anti rust treatment to affected panels.			120.00	90.00	30
4)	To transfer Rh door fittings and attachments.			80.00	60.00	
5)	To putty and spray painting charges.			900.00	700.00	300
Total				10,428.00	9,134.20	
Lump sum repair adjustment					7,300.00	

3 days