



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile CS3/LPC22005489/Kvy3-1

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: ~~CS3/LPC22005489/0~~
Date: ~~09/06/2022~~ 22/08/2022
Code: LPC2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBH 8076M	Veh. Inspected	SDH 3338S
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	09/06/2022 22/08/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	07/06/2022	Inspection Date	
Survey held at	HIAP LEK AUTOMOBILE TRADING 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.