

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 Heavy Vehicle #01-08 Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CICO HOLDINGS (2008) PTE LTD
7 LORONG 11 GEYLANG #01-00
SINGAPORE 388699

Contact : 81189095, 87417671

LICK ADH

45

~~23000.00~~

14 days

7PA.XA

Xiao Tony

TAX INVOICE

Repair Code : CLM17337

Date in : 23 08 2022

Vehicle Num. : GBJ1248U

Model : TOYOTA DYNA 150 5MT

Chassis Eng# : JTFAT35Y70K212000-1KD2833558

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRBAG ECU <i>new</i>	1	950.50	X 950.50
DASHBOARD <i>del</i>	1	1870.20	✓ 1870.20
DASHBOARD CENTER LOWER GARNISH	1	786.90	✓ 786.90
DASHBOARD LH COMPARTMENT TRAY	1	370.10	✓ 370.10
DASHBOARD LH LOWER COVER GARNISH	1	366.70	✓ 366.70
DASHBOARD REINFORCEMENT <i>Best</i>	1	670.90	✓ 670.90
FRONT AIRCON ALUMINIUM PIPE <i>Best</i>	1	187.20	1845 187.20
FRONT AIRCON BLOWER ASSY <i>3 cracked</i>	1	3870.20	3870.20
FRONT AIRCON COOLING COIL ASSY	1	1338.00	✓ 1338.00
FRONT AIRCON DISCHARGE PIPE <i>Best</i>	1	680.90	345 680.90
FRONT BUMPER <i>Distorted</i>	1	895.20	684 895.20
FRONT BUMPER FOGLAMP GARNISH L R <i>LH missing</i>	2	135.00	135 270.00
FRONT BUMPER INNER BRACKET L R <i>LH Best</i>	2	150.50	150.50 301.00
FRONT BUMPER INNER REINFORCEMENT <i>new</i>	1	182.20	X 182.20
FRONT CABIN LH LOCK <i>new</i>	1	423.40	✓ 423.40
FRONT CABIN LH LOCK LATCH <i>new</i>	1	280.90	X 280.90
FRONT CABIN LH LOWER SIDE GARNISH <i>new</i>	1	97.60	X 97.60
FRONT CABIN LOCK CONNECTING <i>new</i>	1	105.70	X 105.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@an51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CICO HOLDINGS (2008) PTE LTD
7 LORONG 11 GEYLANG #01-00
SINGAPORE 388699

Contact : 81189095, 87417671

TAX INVOICE

Repair Code : CLM17337

Date in : 23/08/2022

Vehicle Num. : GBJ1248U

Model : TOYOTA DYNA 150 5MT

Chassis Eng# : JTFAT35Y70K212000-1KD2833558

FRONT CABIN MOUNTING LH	<i>to be</i>	1	504.60	✓	504.60
FRONT CABIN MOUNTING RH	<i>new</i>	1	504.60	✗	504.60
FRONT CABIN MOUNTING SHAFT BRACKET	<i>new</i>	1	180.40	✗	180.40
FRONT CABIN MOUNTING SHAFT SPRING	<i>new</i>	1	373.90	✗	373.90
FRONT CABIN RH LOCK	<i>new</i>	1	423.40	✗	423.40
FRONT CABIN STAY	<i>new</i>	1	180.50	✗	180.50
FRONT CORNER PANNEL L/R	<i>LH Missing</i>	2	336.40	✗	336.40
FRONT DOOR L/R	<i>LH Distorted</i>	2	1794.20	✗	1794.20
FRONT FLOOR PANEL	<i>Regis</i>	1	1970.60	✗	1970.60
FRONT FLOOR PANEL LOWER SIDE GARNISH	<i>Not new</i>	1	570.80	✗	570.80
FRONT GRILLE	<i>cracked</i>	1	595.20	✓	595.20
FRONT GRILLE 'LOGO' EMBLEM	<i>new</i>	1	70.50	✓	70.50
FRONT HEADLAMP L/R	<i>cracked</i>	2	892.90	✓	1,785.80
FRONT LH AIRCON CONDENSER	<i>Distorted</i>	1	950.30	✓	950.30
FRONT LH AIRCON CONDENSER BRACKET	<i>Best</i>	1	67.90	✓	67.90
FRONT LH AIRCON CONDENSER FAN BLADE	<i>new</i>	1	180.70	✗	180.70
FRONT LH AIRCON CONDENSER FAN COWLING	<i>cracked</i>	1	307.80	✓	307.80
FRONT LH AIRCON CONDENSER FAN MOTOR	<i>Don't</i>	1	633.10	✓	633.10

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27
Singapore 417921 Tel No : +65 6842 0051 Fax No : +65 6741 0510
E-Mail : sales@ans1.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CICO HOLDINGS (2008) PTE LTD
7 LORONG 11 GEYLANG #01-00
SINGAPORE 388699

Contact : 81189095, 87417671

TAX INVOICE

Repair Code : CLM17337

Date in : 23 08 2022

Vehicle Num. : GBJ1248U

Model : TOYOTA DYNA 150 5MT

Chassis Eng# : JTFAT35Y70K212000 1KD2833558

FRONT LH AIRCON CONDENSER SIDE BRACKET	Best	1	92.70	✓	92.70
FRONT LH ARCH SHIELD GARNISH	Cracked	1	369.10	✓	369.10
FRONT LH CONTROL ARM	Replaced	1	169.30	✓	169.30
FRONT LH DOOR CHECKER	Replaced	1	183.20	✓	183.20
FRONT LH DOOR GLASS CHANNEL	Best	1	704.80	125 ✓	704.80
FRONT LH DOOR GLASS CHANNEL RUBBER	ut	1	243.70	✓	243.70
FRONT LH DOOR GLASS OUTER MOULDING	Replaced	1	113.60	✓	113.60
FRONT LH DOOR GLASS REGULATOR	Replaced	1	355.40	✓	355.40
FRONT LH DOOR GLASS REGULATOR MOTOR	Damaged	1	355.90	✓	355.90
FRONT LH DOOR HINGE (LOWER)	3 Best	1	110.00	✓	110.00
FRONT LH DOOR HINGE (TOP)		1	110.00	✓	110.00
FRONT LH DOOR INNER LOCK OPENER HANDLE	new	1	89.10	X	89.10
FRONT LH DOOR INNER POWER WINDOW SWITCH	Not in	1	110.40	X	110.40
FRONT LH DOOR INNER PULL GARNISH	new	1	92.70	X	92.70
FRONT LH DOOR INNER RUBBER GUIDE STOPPER	new	2	27.40	X	54.80
FRONT LH DOOR INNER TOP HANDLE BRACKET	Best	1	189.30	✓	189.30
FRONT LH DOOR INNER TRIM BOARD	Distorted	1	858.90	607 ✓	858.90
FRONT LH DOOR INNER TRIM BOARD MOULDING	Not in	1	181.90	X	181.90

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CICO HOLDINGS (2008) PTE LTD
7 LORONG 11 GEYLANG #01-00
SINGAPORE 388699

Contact : 81189095, 87417671

TAX INVOICE

Repair Code : CLM17337

Date in : 23 08 2022

Vehicle Num. : GBJ1248U

Model : TOYOTA DYNA 150 5MT

Chassis Eng# : JTFAT35Y70K212000 1KD2833558

FRONT LH DOOR LOCK STRIKER <i>at m</i>	1	39.30	+	39.30
FRONT LH DOOR MECHANISM LOCK <i>Damaged</i>	1	316.00	✓	316.00
FRONT LH DOOR OUTER FRAME GARNISH <i>Delnd</i>	1	80.10	✓	80.10
FRONT LH DOOR OUTER HANDLE <i>at m</i>	1	110.70	X	110.70
FRONT LH DOOR PILLAR (CENTER) <i>} Distorted</i>	1	292.10	✓	292.10
FRONT LH DOOR PILLAR (INNER) <i>} Distorted</i>	1	465.00	✓	465.00
FRONT LH DOOR PILLAR (OUTER) <i>Distorted</i>	1	414.30	✓	414.30
FRONT LH DOOR PILLAR BRACKET <i>Best</i>	1	49.00	✓	49.00
FRONT LH DOOR WEATHER STRIP <i>at</i>	1	243.70	✓	243.70
FRONT LH DOOR WEATHER STRIP ARCH <i>} cut</i>	1	186.80	✓	186.80
FRONT LH DOOR WEATHER STRIP VERTICAL <i>} cut</i>	1	115.30	✓	115.30
FRONT LH DOOR WINDOW GLASS <i>Shattered</i>	1	692.70	✓	692.70
FRONT LH KNUCKLE ARM <i>} Damd</i>	1	625.90	✓	625.90
FRONT LH KNUCKLE ARM BEARING	1	787.80	✓	787.80
FRONT LH LOWER ARM <i>Best</i>	1	1029.60	767	1029.60
FRONT LH PASSENGER AIRBAG <i>no m</i>	1	4870.40	X	4870.40
FRONT LH PILLAR ARCH GARNISH <i>Delnd</i>	1	270.90	✓	270.90
FRONT LH PILLAR ARCH RUBBER MOULDING <i>Delnd</i>	1	110.70	✓	110.70

*** This is a computer-generated document which requires no signature. ***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27
Singapore 417921 Tel No : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@an51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CICO HOLDINGS (2008) PTE LTD
7 LORONG 11 GEYLANG #01-00
SINGAPORE 388699

Contact : 81189095, 87417671

TAX INVOICE

Repair Code : CLM17337

Date in : 23 08 2022

Vehicle Num. : GBJ1248U

Model : TOYOTA DYNA 150 5MT

Chassis Eng# : JTFAT35Y70K212000-1KD2833558

FRONT LH PILLAR WEATHER STRIP	at	1	170.20	✓	170.20
FRONT LH SHOCK ABSORBER	Best	1	107.70	✓	107.70
FRONT LH SIDE MIRROR WITH MOTOR ASSY	Damaged	1	1128.00	✓	1,128.00
FRONT LH STEP GARNISH	Del'd	1	302.80	✓	302.80
FRONT LH TIE ROD END	del'd	1	351.90	+	351.90
FRONT LH UPPER ARM	del'd	1	1720.80	+	1,720.80
FRONT LH WHEEL RIM	del'd	1	480.00	+	480.00
FRONT PANEL	Rep'd	1	1194.30	+	1,194.30
FRONT PANEL 'DYNA' EMBLEM	del'd	1	89.90	✓	89.90
FRONT WINDSCREEN	Shattered	1	980.30	✓	980.30
FRONT WINDSCREEN MOULDING	del'd	1	327.60	✓	327.60
FRONT WIPER PANEL	Rep'd	1	311.80	+	311.80
REAR PILLAR LH	Rep'd	1	639.50	+	639.50
ROOF TOP SUN VISOR LH	Del'd	1	325.00	✓	325.00
ROOF TOP UPHOLSTERY	Completed	1	859.00	✓	859.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27
 Singapore 417921 Tel No : +65 6842 0051 Fax No : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

CICO HOLDINGS (2008) PTE LTD
 7 LORONG 11 GEYLANG #01-00
 SINGAPORE 388699

Contact : 81189095, 87417671

TAX INVOICE

Repair Code : CLM17337

Date in : 23 08 2022

Vehicle Num. : GBJ1248U

Model : TOYOTA DYNA 150 5MT

Chassis Eng# : JTFAT35Y70K212000 1KD2833558

		Subtotal before discount	26021.00	51,282.80
Percentage discount	25%		12,820.70	
		Sub-total 1	28,442.40	38,462.10
FRONT BUMPER NUMBER PLATE	NEU	1	25.00	X 25.00
FRONT DOOR 3D STICKER L R	NEU	2	480.00	280 960.00
FRONT DOOR COMPANY STICKER L R	NEU	2	25.00	30 50.00
FRONT FLOOR PANEL INSULATOR MAT	NEU	1	300.00	X 300.00
FRONT GRILLE CLIPS - SET	NEU	1	50.00	20 50.00
FRONT HEADLAMP CLIPS L R - SET	NEU	2	25.00	20 50.00
FRONT LH DOOR INNER TRIM BOARD CLIPS - SET	NEU	1	40.00	30 40.00
FRONT LH TYRE	NEU	1	400.00	180 400.00
FRONT PANEL 3D STICKER	NEU	1	480.00	250 480.00
		Subtotal before discount		2,355.00
Percentage discount	0%			0.00
		Sub-total 2		2,355.00
		Parts-total		40,817.10

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, change air bag, air-bag sensor, air-bag wire and resetting system.

80 140.00
 30 80.00
 250 300.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CICO HOLDINGS (2008) PTE LTD
7 LORONG 11 GEYLANG #01-00
SINGAPORE 388699

Contact : 81189095, 87417671

TAX INVOICE

Repair Code : CLM17337
Date in : 23 08 2022
Vehicle Num. : GBJ1248U
Model : TOYOTA DYNA 150 5MT
Chassis Eng# : JTFAT35Y70K212000-1KD2833558

To remove, change windscreen.	120	150.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	200	280.00
To road test driving, check and resetting wheel alignments system.	80	100.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	✓	100.00
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	80	140.00
To remove, change dashboard fascia and transfer where necessary.	220	300.00
To re-spray painting on the change body parts, repair portion, and where consistent to the accident.	2000	2,000.00
To provide labour, workmanship to change the above damaged body parts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1800	3,000.00
To apply anti-rust chemical on repaired and replaced panel.	120	180.00
Labour Total	5080	7,370.00
Parts & Labour Total		48,187.10

*** This is a computer-generated document which requires no signature.***

page 7

total: 27231.80
4/5 21.8K
14 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

21.8K