

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Dup 10k.

CoE under 20-01-2023 Bal Smk.

NOT 82477

4/5 @ 1600 informed Jones

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412
Singapore 539195
Tel: 62898126 Fax : 62870590
Email: Jin@jinauto.com.sg
Company Reg No:200704370C GST Reg No :200704370C

not afford
her
2/5 \$1600/
4 days
31/08/22

24/8/2022

M/S ALLIANZ

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR MITSUBISHI LANCER- SJB6793B

DOA : 19/08/2022

S/N	QTY	DESCRIPTION		
1	1 PC	REAR BUMPER <i>Dis</i>	\$	815.00 ✓
2	10 PCS	REAR BUMPER CLIPS <i>all</i>	\$	50.00 ✓
3	1 PC	REAR BUMPER TOW COVER <i>To.1</i>	\$	29.00 ✓
4	1 PC	REAR BUMPER RED REFLECTOR - RH <i>11</i>	\$	28.00 X
5	1 PC	REAR BUMPER RED REFLECTOR - LH <i>11</i>	\$	28.00 X
6	1 PC	END PANEL <i>R</i>	\$	506.00 X
7	1 PC	END PANEL TOP GARNISH <i>11</i>	\$	169.00 X
8	1 PC	REAR BOOTLID <i>R</i>	\$	REPAIR X
9	1 PC	REAR BOOTLID WEATHERSTRIP (RUBBER) <i>11</i>	\$	186.00 X
10	1 PC	SPARETYRE PANEL <i>11</i>	\$	REPAIR X
			\$	1811.00
			Disc -20%	\$ -362.20
				\$ 1448.80
11		SPRAY PAINTING	\$	1200.00 <i>600</i>
12		LABOUR CHARGE	\$	780.00 <i>400</i>
13	<i>1 set</i>	REVERSE SENSOR <i>short</i>	\$	280.00 <i>200 s/w</i>
14		LABOUR FOR REVERSE SENSOR	\$	80.00 <i>50</i>
15		TUFF COAT	\$	<i>11</i> 80.00 X
16		REAR NUMBER PLATE	\$	<i>Best</i> 35.00 ✓ <i>s/w</i>
17		WIRING	\$	35.00 <i>20</i>
			\$	3938.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

2-884
202
715.20
1305
2020.2
1616.