

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub

Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

TP INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)
ZHANG ZHIWEI RUDY

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	WH1398
Policy No:		Date of Loss:	24/08/2022
Vehicle Reg. No.:	SLV8538E	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	NISSAN ALMERA, 1.5 5MT AIRBAG 2WD 4DR (A)	Vehicle Reg. Date:	30/05/2016
Vehicle Colour:	GREY		
Engine No:	HR15929391D	Chassis No:	MNTBBAN17Z0005590
Odometer:	266100 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	3,179.00
Miscellaneous Items	475.00
Labour	2,680.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	6,334.00
+ GST 7.00% (S\$)	443.38
Nett Amount (S\$)	6,777.38

This claim is handled by: CHAN PEI PEI

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Aug 2022)

Parts: 143 NISSAN ALMERA 1.5 5MT AIRBAG 2WD 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Wah Hong Motors & Credit Pte Ltd/SLV8538E/25/08/2022 17:52

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Boot lid <i>bt</i>	0.00	0.00	*450.00 F
2	1		*Boot lid hinge RH/LH@2*\$70 <i>bt</i>	0.00	0.00	*140.00 F
3	1		*Boot lid lock <i>bt</i>	0.00	0.00	*60.00 F
4	1		*Boot lid logo badge <i>new X an</i>	0.00	0.00	*40.00 F <i>X</i>
5	1		*Boot lid emblem Almera <i>new</i>	0.00	0.00	*40.00 F
6	1		*Boot lid weather stripe <i>new</i>	0.00	0.00	*60.00 F
7	1		*End panel <i>bt</i>	0.00	0.00	*230.00 F
8	1		*End panel top garnish <i>? de</i>	0.00	0.00	*100.00 F
9	1		*Tail lamp RH/LH@2*\$150 <i>LH-4/RH-cm</i>	0.00	0.00	*300.00 F
10	1		*Rear fender RH <i>new</i>	0.00	0.00	*750.00 F
11	1		*Rear reinforcement beam RH/LH@2*\$70 <i>LH-X/RH-bt</i>	0.00	0.00	*140.00 F <i>70</i>
12	1		*Rear bumper <i>cut</i>	0.00	0.00	*280.00 F
13	1		*Rear bumper side retainer RH/LH@2*\$35 <i>new</i>	0.00	0.00	*70.00 F
14	1		*Spare tyre top cover <i>de</i>	0.00	0.00	*230.00 F
15	1		*Rear fender LH (Repair refer to labour)	0.00	0.00	*- F
16	1		*Rear floor panel (Repair refer to labour)	0.00	0.00	*- F

F=Franchise part.

Sub Total (\$\$)	2,890.00
+ Margin on L,N Items 10.00% (\$\$)	289.00
Total Parts (\$\$)	3,179.00

Wah Hong Motors & Credit Pte Ltd/SLV8538E/25/08/2022 17:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Boot lid insulator clips <i>NE</i>	25.00 ✓
2	1	End panel sealant <i>NE</i>	40 60.00
3	1	Rear bumper clips <i>NE</i>	30 35.00
4	1	Rear car plate with holder <i>CM</i>	35.00 ✓
5	1	Rear fender RH sealant <i>NE</i>	40 60.00
6	1	Rear reverse sensor <i>CM</i>	200.00 ✓
7	1	Rear windscreen sealant <i>NE</i>	40 60.00
Sub Total (S\$)			475.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New <i>1000</i>	1,200.00 ✓
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New <i>800</i>	1,000.00 ✓
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New <i>30</i>	60.00 ✓
4	To remove and replace rear reverse sensor	New <i>40</i>	100.00 ✓
5	To remove and refit rear seat in order to repair	New <i>60</i>	100.00 ✓
6	To remove and refit upholstery garnish & roofs lining in order to repair	New <i>60</i>	100.00 ✓
7	To remove and refit rear windscreen	New <i>2110</i>	120.00 ✓
Gross Labour Cost (S\$)			2,680.00

Wah Hong Motors & Credit Pte Ltd/SLV8538E/25/08/2022 17:52. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

3058
410
2110
5578
20%
4462.40
4/8 - \$4,450 / 8 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
Hp 90010068
8 days
4/8
26/08/22 P1210
Resy after repair