

ACC. REC. BY: T. J. J. J.

REF:

CC3/ AIG 22008250/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated cost: _____

☒ OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/ehicle No: _____

at Worksp m/s _____

of _____

Insured: _____

Policy No. 2070149801

Claims No. 0859248373SG

Sum Insured: _____ Excess: 700

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 9180K.

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: Kee Siang Vehicle: IN / OUT

Veh No: SMV 91084

Yr Regn: 2020, Oct

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A5

C.C. 1984

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 32242

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WU4 227 F57 M4 005 956

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40 R18

R: 7 1

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 19/8/2022

D.O.I. 25/8/22

Survey held at Premium Ubi

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

4/11/22 Final fig \$14,284.80 confirmed by email (red 22,890.20, 61%)

Date/Time, File Pass 107

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 16/11/22-typist

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: Merimen

Lump Sum / L.B. / C: \$14,284.80

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0721/2022/EQ
DATE : 20-Aug-22
WIP : 38228

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. CHAN SONG KIA
ADDRESS : BLK 163 BEDOK SOUTH ROAD
#09-434
SINGAPORE 460163
TELEPHONE : HP +65 94557555
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070149801
VEHICLE NO : **SMV 9108 U**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI
MODEL YEAR : 27/10/2020
ENGINE NO : DEM 025899
CHASSIS NO : WAUZZZF57MA005956
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Aug-22
PLACE OF ACCIDENT : BEDOK SOUTH ROAD (CARPARK)


ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 9108 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	450.00	✓
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,700.00	?
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00	?
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	380.00	X
6	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,500.00	1000
SUB-TOTAL LABOUR CHARGES		:	\$ 9,710.00	



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 9108 U

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RESPRAY FRONT BUMPER, [✓] RHS FRONT FENDER AND [✓] RHS FRONT DOOR.	\$ 3,500.00	1100
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$ 384.00	✓
TOTAL LABOUR CHARGES		: \$ 13,594.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9108 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,493.00	de ✓
2	FRONT BUMPER SECURING STRIP	2	\$ 79.00	X
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	X
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 293.00	X
5	FRONT BUMPER SPOILER	1	\$ 599.00	?
6	FRONT RADIATOR AIR GUIDE - RH	1	\$ 72.00	de ✓
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00	X
8	RADIATOR AIR GUIDE GRILLE - RH	1	\$ 151.00	de ✓
9	FRONT BUMPER MOLDING TRIM STRIP - RH	1	\$ 54.00	X
10	FRONT TRIM - CENTER	1	\$ 127.00	X
11	RADIATOR GRILLE	1	\$ 1,881.00	X
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00	?
13	FRONT BUMPER CARRIER	1	\$ 899.00	?
14	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	19 ✓
15	FRONT BUMPER TOP COVER	1	\$ 143.00	X
16	CAUTION SIGN STICKER	1	\$ 16.00	X
17	AIR CONDITIONER STICKER	1	\$ 9.00	X
18	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00	?
19	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	?
20	FRONT LOW TONE HORN BRACKET - RH	1	\$ 139.00	X
SUB TOTAL SPARE PARTS		:	\$ 7,889.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9108 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT LOW TONE HORN MOUNT BRACKET	1	\$ 33.00	X
22	FRONT PARKING AID SENSOR - OUTER	1	\$ 266.00	?
23	FRONT PARKING AID SENSOR - SIDE	1	\$ 266.00	?
24	FRONT PARKING AID SEAL RING	4	\$ 10.00	nee
25	FRONT BUMPER WIRING SET	1	\$ 449.00	?
26	FRONT FENDER - RH	1	\$ 1,189.00	bt
27	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00	X
28	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 83.00	?
29	FRONT FENDER BRACKET - RH	1	\$ 41.00	?
30	FRONT FENDER RIVET	6	\$ 23.00	nee
31	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$ 55.00	?
32	FRONT FENDER BRACE - RH	1	\$ 132.00	?
33	FRONT FENDER TRIM - RH	1	\$ 171.00	nee
34	FRONT FENDER LEDGE COVER	1	\$ 40.00	?
35	FRONT FENDER LEDGE COVER - RH	1	\$ 18.00	?
36	HEADLIGHT COVER - RH	1	\$ 49.00	?
37	FRONT WHEEL HOUSING LINER - RH	1	\$ 299.00	?
38	FRONT WHEEL SPOILER - RH	1	\$ 82.00	?
39	FRONT WHEEL SPOILER TRIM - RH	1	\$ 40.00	?
40	FRONT STONE CHIP GUARD - RH	1	\$ 57.00	X
SUB TOTAL SPARE PARTS		:	\$ 3,358.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9108 U

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER INNER LOWER BRACKET - RH	1	\$ 27.00	?
42	HEADLIGHT - RH	1	\$ 8,172.00	Chet ✓
43	HEADLIGHT HOSE	1	\$ 42.00	?
44	HEADLIGHT COMPENSATING PIECE	3	\$ 137.00	?
45	LIFT CYLINDER - RH	1	\$ 217.00	?
46	LIFT CYLINDER BRACKET - RH	1	\$ 17.00	?
47	LIFT CYLINDER WASHER HOSE	1	\$ 107.00	?
48	HEADLIGHT WASHER HOSE	1	\$ 53.00	?
49	FRONT SHIELD NOISE INSULATION	1	\$ 640.00	?
50	LOCK CARRIER	1	\$ 1,127.00	?
51	RADIATOR COOLANT REGULATOR SUPPORT - RH	1	\$ 43.00	?
52	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	?
53	FRONT INTER-COOLER HOSE - RH	1	\$ 413.00	?
54	RADIATOR AIR GUIDE - RH	1	\$ 36.00	?
55	RADIATOR AIR GUIDE - LH / RH	2	\$ 38.00	?
56	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 44.00	?
57	FRONT DOOR TRIM - RH	1	\$ 171.00	?
58	FRONT WINDOW SLOT SEAL TRIM STRIP - RH	1	\$ 446.00	?
59	FRONT NO PLATE	S/N	\$ 60.00	X
60	SUNDRIES		\$ 500.00	?
TOTAL SPARE PARTS		:	\$ 23,558.00	
TOTAL LABOUR CHARGES		:	\$ 13,594.00	
GRAND TOTAL		:	\$ 37,152.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Tanpin 97495749
Not Authorise, Newt 25/8/22 01070
Ex: to be advise
Resurvey before paint 05 days
Tanpin @ Kluantan

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT