

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0721/2022/EQ
DATE : 20-Aug-22
WIP : 38228

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 25/8/2022.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

*Hi Taufikh
5 days - ok - Johnny Boo
31-Oct-22*

OWNER'S NAME : MR. CHAN SONG KIA
ADDRESS : BLK 163 BEDOK SOUTH ROAD
#09-434
SINGAPORE 460163
TELEPHONE : HP +65 94557555
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070149801
VEHICLE NO : **SMV 9108 U**
MODEL CODE : AUDI A5 SPORTBACK 2.0 TFSI
MODEL YEAR : 27/10/2020
ENGINE NO : DEM 025899
CHASSIS NO : WAUZZZF57MA005956
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Aug-22
PLACE OF ACCIDENT : BEDOK SOUTH ROAD (CARPARK)

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 9108 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	450.00	\$ 450.00
3	TO REMOVE AND REINSTALL AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM.	S/N \$	1,700.00	
4	TO CARRY OUT VACUUM AND REGAS FOR R1234.	S/N \$	1,200.00	
5	TO REMOVE AND REINSTALL RHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL RHS WING MIRROR ASSY TO FACILITATE RESPRAY OF RHS FRONT DOOR.	S/N \$	380.00	
6	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. TO REPAIR RHS FRONT DOOR. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,500.00	\$ 1,000.00
SUB-TOTAL LABOUR CHARGES		:	\$ 9,710.00	\$ 1,930.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 9108 U

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
		<i>c/f</i>		\$ 1,930.00
7	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER AND RHS FRONT DOOR.	\$	3,500.00	\$ 1,100.00
8	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 13,594.00	\$ 3,414.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9108 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,493.00	\$	1,994.40
2	FRONT BUMPER SECURING STRIP	2	\$ 79.00		
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	\$	174.80
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 293.00		
5	FRONT BUMPER SPOILER	1	\$ 599.00		
6	FRONT RADIATOR AIR GUIDE - RH	1	\$ 72.00	\$	57.20
7	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00		
8	RADIATOR AIR GUIDE GRILLE - RH	1	\$ 151.00	\$	120.40
9	FRONT BUMPER MOLDING TRIM STRIP - RH	1	\$ 54.00	\$	42.64
10	FRONT TRIM - CENTER	1	\$ 127.00		
11	RADIATOR GRILLE	1	\$ 1,881.00		
12	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00		
13	FRONT BUMPER CARRIER	1	\$ 899.00		
14	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	\$	32.24
15	FRONT BUMPER TOP COVER	1	\$ 143.00		
16	CAUTION SIGN STICKER	1	\$ 16.00		
17	AIR CONDITIONER STICKER	1	\$ 9.00		
18	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00		
19	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00		
20	FRONT LOW TONE HORN BRACKET - RH	1	\$ 139.00		
SUB TOTAL SPARE PARTS		:	\$ 7,889.00	\$	2,421.68

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9108 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>2,421.68</i>
21	FRONT LOW TONE HORN MOUNT BRACKET	1	\$ 33.00		
22	FRONT PARKING AID SENSOR - OUTER	1	\$ 266.00		
23	FRONT PARKING AID SENSOR - SIDE	1	\$ 266.00	<i>\$</i>	<i>212.00</i>
24	FRONT PARKING AID SEAL RING	4	\$ 10.00	<i>\$</i>	<i>8.00</i>
25	FRONT BUMPER WIRING SET	1	\$ 449.00		
26	FRONT FENDER - RH	1	\$ 1,189.00	<i>\$</i>	<i>951.20</i>
27	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00		
28	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 83.00	<i>\$</i>	<i>65.84</i>
29	FRONT FENDER BRACKET - RH	1	\$ 41.00	<i>\$</i>	<i>32.72</i>
30	FRONT FENDER RIVET	6	\$ 23.00		
31	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$ 55.00		
32	FRONT FENDER BRACE - RH	1	\$ 132.00	<i>\$</i>	<i>105.20</i>
33	FRONT FENDER TRIM - RH	1	\$ 171.00	<i>\$</i>	<i>136.40</i>
34	FRONT FENDER LEDGE COVER	1	\$ 40.00		
35	FRONT FENDER LEDGE COVER - RH	1	\$ 18.00		
36	HEADLIGHT COVER - RH	1	\$ 49.00		
37	FRONT WHEEL HOUSING LINER - RH	1	\$ 299.00	<i>\$</i>	<i>238.80</i>
38	FRONT WHEEL SPOILER - RH	1	\$ 82.00	<i>\$</i>	<i>65.12</i>
39	FRONT WHEEL SPOILER TRIM - RH	1	\$ 40.00		
40	FRONT STONE CHIP GUARD - RH	1	\$ 57.00	<i>\$</i>	<i>45.28</i>
SUB TOTAL SPARE PARTS		:	\$ 3,358.00	<i>\$</i>	<i>4,282.24</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 9108 U

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>4,282.24</i>
41	FRONT FENDER INNER LOWER BRACKET - RH	1	\$ 27.00		
42	HEADLIGHT - RH	1	\$ 8,172.00	<i>\$</i>	<i>6,537.60</i>
43	HEADLIGHT HOSE	1	\$ 42.00		
44	HEADLIGHT COMPENSATING PIECE	3	\$ 137.00		
45	LIFT CYLINDER - RH	1	\$ 217.00		
46	LIFT CYLINDER BRACKET - RH	1	\$ 17.00	<i>\$</i>	<i>12.88</i>
47	LIFT CYLINDER WASHER HOSE	1	\$ 107.00		
48	HEADLIGHT WASHER HOSE	1	\$ 53.00		
49	FRONT SHIELD NOISE INSULATION	1	\$ 640.00		
50	LOCK CARRIER	1	\$ 1,127.00		
51	RADIATOR COOLANT REGULATOR SUPPORT - RH	1	\$ 43.00		
52	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00		
53	FRONT INTER-COOLER HOSE - RH	1	\$ 413.00		
54	RADIATOR AIR GUIDE - RH	1	\$ 36.00		
55	RADIATOR AIR GUIDE - LH / RH	2	\$ 38.00		
56	RADIATOR AIR GUIDE - UPPER / LOWER	2	\$ 44.00		
57	FRONT DOOR TRIM - RH	1	\$ 171.00		
58	FRONT WINDOW SLOT SEAL TRIM STRIP - RH	1	\$ 446.00		
59	FRONT NO PLATE	S/N	\$ 60.00		
60	SUPPLEMENTARY		\$ 23.00	<i>\$</i>	<i>18.40</i>
61	SUNDRIES		\$ 500.00	<i>\$</i>	<i>19.68</i>
TOTAL SPARE PARTS		:	\$ 23,581.00	<i>\$</i>	<i>10,870.80</i>
TOTAL LABOUR CHARGES		:	\$ 13,594.00	<i>\$</i>	<i>3,414.00</i>
GRAND TOTAL		:	\$ 37,175.00	<i>\$</i>	<i>14,284.80</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-06/10/22



55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183
Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0721/2022/EQ 26-Sep-22 CHANG 1 of 1 SMV 9108 U AUDI A5 SPORTBACK 2.0 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	HORN WIRE CONNECTOR	\$ 23.00	\$ 18.40
	GRAND TOTAL	\$ 23.00	\$ 18.40

For Premium Automobiles Pte Ltd

Authorised Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT