

AGS. RECVY: Taufikh

REF:

NS/INC 22008253/Tvc

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/ehide No: _____

at Workshop m/s _____

of _____

Insured: **SMV 2552R**

Policy No. _____

Claims No. **MT/1185875-002**


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

1DAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

WP

Date: _____ Person Contacted: Chay

Vehicle: IN / OUT

Veh No: SHD4089C Yr Regn: 2019 at

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai C.C. 1580

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 267409 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: UMHC857C124187739

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 25/8/2022 D.O.I. 25/8/22

Survey held at Compt Layer

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

12/10/22 Taufikh informed LS \$950 (red 1219.80, 56%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 12/10/22-typist

Days Of Repair: 2

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Invs (\$

☐ : Weekend (\$

Report Format: TP

Lump Sum / LS: \$950

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHD4089C

25.08.2022

MAKE REG 30.10.2019

CHIANG/ NUTC

MODEL IONIQ G3

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		Rx \$459.40
2	REAR BUMPER SIDE BRACKET RH		x \$55.80
1	REAR BUMPER REINFORCEMENT		? \$394.80
1	REAR BUMPER CENTRE MOULDING		de \$451.25
2	REAR BUMPER REFLECTOR RH		x \$41.50
10	REAR BUMPER CLIPS		\$2.20 per \$22.00
	SUB TOTAL		\$1,424.75
	20.00%		\$284.95
	DISCOUNTED TOTAL		\$1,139.80
1	REAR REVERES SENSOR		\$180.00
1	REAR NUMBER PLATE W/ HOLDER		laser \$55.00
1	REAR FENDER ADVERTISEMENT		laser \$100.00
1	REAR BUMPER ADVERTISEMENT		laser \$50.00
			\$361.50
	Labour Charge		
	Panel Beating		350 \$550.00
	Spray Painting Charge		250 \$300.00
	Check Lighting and Wiring		x \$60.00
	Tuff Kote		x \$60.00
	Remove/refix Reverse sensor		30 \$60.00
	TOTAL LABOUR		\$1,030.00
	ESTIMATE TOTAL		\$2,169.80
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanphu 97495749
 'wp' 25/8/22 @ 4pm
 L/S Rising after repair
 tanphu@lkharts.com
 - 2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 25.08.2022 11:26

Page : 1

am: ARC Repair TP(CLS0)1

JOB CARD Sales Order: 4657466

JC No: 305527674

STOMER

V/MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045

DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755 (R) (O)

(P)

SCOUNT CARD NO.

REGN NO.: SHD4089C

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL: IONIQ(G3)

DATE/TIME IN: 25.08.2022 08:50

YR OF MANU.: 30.10.2019

TARGET DATE

CHASSIS CODE: RMHC851CVLU187739


COMPLETION DATE/TIME:

ccident Date: 25.08.2022
ATURE: 3P 25.08.2022

/NO LABOR CODE

JOB DESCRIPTION

DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

:
):
e No.: SHD4089C CHIANG

Vehicle No.: SHD4089C

of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard