

NS/INC22008254/Tqc

A.C.S. REC'DY: Taufik

REF:

INC

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / IS / TP RES / OD RES / EVA / INV / MV

To Inspect/ehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: Sumaw

Vehicle: IN / OUT

Veh No: SH6037MYr Regn: 2017 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota PriusC.C. 1798Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 66805

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 3TDKBSF4 003563773

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15R: 24

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Wastake

Front

Rear

R/Bal. 6 mmR/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mm

D.O.A. _____

D.O.I. 23/08/2022Survey held at Comfort Loggia

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Taufik finalised LS \$3850, 3 days. (Red \$4283.36, 53%)

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Report Formet: TPLump Sum / H.R. / 3850

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH 6037M

MAKE TOYOTA

MODEL PRIUS

DATE: 23.08.22

MVA JUMANI

DOA: 19.08.22

NTUC (USAM)

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR FENDER RH			\$992.04
1	REAR DOOR ASSY RH			\$1,258.30
1	REAR DOOR GLASS RH			\$780.50
1	REAR DOOR REGULARTOR RH			\$228.40
1	REAR DOOR POWER MOTOR			\$941.80
1	REAR DOOR CHECK RH			\$153.00
1	REAR BUMPER ASSY			\$503.04
1	REAR BUMPER SIDE BRACKET RH			\$94.80
10	REAR BUMPER CLIPS			\$22.00
1	REAR DOOR HINGE UPPER RH			\$82.30
1	REAR DOOR HINGE LOWER RH			\$82.30
	ROCKER PANEL GARNISH RH			\$576.00
	TAILLAMP ASSY RH			\$570.00
	SUB TOTAL			\$6,284.48
	LESS 25%			\$1,571.12
	DISCOUNTED TOTAL			\$4,713.36
	REAR DOOR APPS LOGO			\$80.00
	ADVERTISEMENT LOGO- BUMPER			\$100.00
	ADVERTISEMENT LOGO- FENDER			\$200.00
	ADVERTISEMENT LOGO - DOOR			\$100.00
				\$480.00
	Labour Charge			
	PANEL BEATING			\$1,400.00
	SPRAY PAINT			\$1,200.00
	REMOVE / REFIX DOOR PARTS			\$120.00
	TUFF KOTE			\$50.00
	REMOVE/REFIX REAR UPHOSLERY			\$120.00
	cheek wiring			\$500.00
	TOTAL LABOUR			\$8,086.36
	ESTIMATE TOTAL			\$6,830.43
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tan Jhi 97495747
 with 24/8/22 @ 445
 c/s proxy after repair

Date/Time: 22.08.2022 16:22

Page : 1

m: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4631065

JC NO: 305527397

COMER

IS COMFORT TRANSPORTATION PTE LTD

COMER NO. 7010045

RESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65508755

(O)

(P)

OUNT CARD NO.

REGN NO.:

SH 6037M

MILEAGE

MAKE:

TOYOTA

FUEL

E.....1/2.....F

MODEL

PRIUS HYBRID(G4)22.08.2022 16:01

DATE/TIME IN

YR OF MANU.

07.09.2017

TARGET DATE

CHASSIS CODE

JTDKB3FU003563773

COMPLETION DATE/TIME:

ident Date: 19.08.2022


URE: 3P 19.08.22/C

VO

LABOR CODE

JOB DESCRIPTION

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vo.: SH 6037M

JU NTUC

Vehicle No.:

SH 6037M

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard