

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

Lee / Admin

SIM AIK SIN
BLK 12 TECK WHYE LANE #14-218
SINGAPORE 680012

Contact : 87802550

TAX INVOICE

TP Allianz
Hui Rong

Repair Code : CLM15634
Date in : 24/08/2022
Vehicle Num. : SLK2031Y
Model : HONDA CIVIC TYPE-R 2.0 M
Chassis/Eng# : FD21400529/K20A5820549

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>torn</i>	1	873.90	✓ 873.90
FRONT BUMPER LOWER LID GARNISH <i>Not new</i>	1	450.00	X 450.00
FRONT BUMPER SIDE RETAINER L/R <i>RH Damaged</i>	2	28.90	28.90 57.80
FRONT RH FENDER INNER SHIELD <i>torn</i>	1	127.40	✓ 127.40
FRONT RH FENDER LAMP <i>Not new</i>	1	39.40	X 39.40
FRONT RH HEADLAMP <i>cracked</i>	1	1100.40	✓ 1,100.40
FRONT RH HEADLAMP LOWER BRACKET <i>Not new</i>	1	29.10	X 29.10
FRONT RH KNUCKLE ARM <i>Not new</i>	1	295.70	X 295.70
FRONT RH KNUCKLE ARM BEARING <i>Damaged</i>	1	112.40	✓ 112.40
FRONT RH LOWER ARM <i>Best</i>	1	450.80	✓ 450.80
FRONT RH LOWER ARM BALL JOINT <i>Not new</i>	1	93.40	X 93.40
FRONT RH SIDE MIRROR <i>Not new</i>	1	360.40	X 360.40
FRONT RH STEERING TIE ROD <i>Not new</i>	1	87.90	X 87.90
FRONT RH STEERING TIE ROD END <i>Not new</i>	1	82.40	X 82.40
FRONT RH WHEEL HUB <i>Damaged</i>	1	249.50	✓ 249.50

*** This is a computer-generated document which requires no signature.***

Autonub
Sukit Ave 2
#01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
ST Registration No. : 200714616M

SIM AIK SIN
BLK 12 TECK WHYE LANE #14-218
SINGAPORE 680012

Contact : 87802550

TAX INVOICE

Repair Code : CLM15634

Date in : 24/08/2022

Vehicle Num. : SLK2031Y

Model : HONDA CIVIC TYPE-R 2.0 M

Chassis/Eng# : FD21400529/K20A5820549

	Subtotal before discount	2943.30	4,410.50
Percentage discount 20%		2354.64	882.10
	Sub-total 1		3,528.40
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	30 50.00
FRONT BUMPER STICKER <i>new</i>	1	80.00	30 80.00
FRONT RH FENDER <i>Dented.</i>	1	1500.00	900. 1,500.00
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	30 50.00
FRONT RH SPORT RIM <i>lit</i>	1	900.00	500 900.00
FRONT RH TYRE <i>new</i>	1	400.00	X 400.00
FRONT SHOCK ABSORBER - SET <i>new</i>	1	1800.00	X 1,800.00
	Subtotal before discount		4,780.00
Percentage discount 0%			0.00
	Sub-total 2		4,780.00
	Parts-total		8,308.40

LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, reinstall front suspension undercarriage parts. (to FR)

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

~~30~~ 60.00
~~150~~ 220.00
~~80~~ 100.00
~~500~~ 1,000.00
~~500~~ 700.00

*** This is a computer-generated document which requires no signature.***

M AIK SIN
K 12 TECK WHYE LANE #14-218
SINGAPORE 680012

Contact : 87802550

TAX INVOICE

Repair Code : CLM15634

Date in : 24/08/2022

Vehicle Num. : SLK2031Y

Model : HONDA CIVIC TYPE-R 2.0 M

Chassis/Eng# : FD21400529/K20A5820549

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1300	40. 50.00
		2,130.00
Parts & Labour Total		10,438.40

*** This is a computer-generated document which requires no signature.***

page 3

Adrian Lj
25/08/22 4/s.
05 Days

total: 5244.64
L/s: 4.2K

4.2K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: