



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22008265/Kcy3m4 Date: 16/09/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 1875E	Veh. Inspected	FBS 9283S	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/08/22/2064	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	26/08/2022	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA R15 (M)	c.c	155	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	ME1RG6714M0092897	Colour	METALLIC RED	
Odometer	18169 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70 R17	MAXXIS	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	140/70 R17	MAXXIS	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION & O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	23/08/2022	Inspection Date	26/08/2022	
Survey held at	SG 98 MOTOR PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	