



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms Choong Chee Chui	Cust No/Name	/Ms CHOONG CHEE CHUI
BLK 279 TOH GUAN ROAD	Reg No/Reg Date	SMQ4231E / 15/11/201
#15-193	Date In/Mileage	/ 0
SINGAPORE 600279	Chassis No	KNAF5416ML5052977
	Engine No	G4FGKH749532
Contact No Mobile: 98715246	Make/Model	KIA/CERATO 1.6 A GT LINE H171
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00081	Cash	24/08/2022/ 11:37		442 / CocoLu	56342		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							640.00
RENEW FRT BUMPER, FRT BUMPER LOWER GRILLE							
E PNT98000							550.00
SPRAY PAINT FOR FRT BUMPER							
E PNT88000							60.00
REMOVE & INSTALL PARKING SENSOR							
A 90000001							50.00
CHECK WIRING & ELECTRICAL SYSTEM							
A 10028901							280.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM							
M SUNDRY							20.00
Sundry							
M COVER-FR BUMPER	✓	00		1.00	633.00	00.00	633.00
M GRILLE-FRONT BUMPER	✓	00		1.00	669.00	00.00	669.00
M MOULDING-FRONT BUMPER,RH	✗	CUT		1.00	298.00	00.00	298.00
M LAMP ASSY-SIDE REPEATER,RH	✗	CUT		1.00	226.00	00.00	226.00
M AIR DUCT-FR BUMPER,RH	✗	NN		1.00	14.00	00.00	14.00
M BRACKET-FR BUMPER UPR SIDE MTG	✗	NN		1.00	31.00	00.00	31.00
M ABSORBER-FRONT BUMPER ENERGY	✗	NN		1.00	84.00	00.00	84.00
M STIFFNER-FR BPR LWR	✗	NN		1.00	114.00	00.00	114.00
M BEAM COMPLETE-FR BUMPER	✗	NN		1.00	686.00	00.00	686.00
M ORNAMENT-KIA NO.115	✗	NN		1.00	38.00	00.00	38.00
M ULTRASONIC SENSOR ASSY-P.A.S	✗	NN		1.00	163.00	00.00	163.00

Stem (LKK)

26/9/22, 1:30p

WZK

3 Lys

P/P

by BL y

Confirm & accepted by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Authorized signatory and company stamp

	Nett	4,556.00
7% GST on	4556.00	318.92
Total	Payable	4,874.92

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.