

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIS22008273/UPA3Q2**Date:** 11/11/2022REFERENCE

Handling Insurer:	Allianz Insurance Singapore Pte. Ltd.	Policy No:	SP2002218177
Claimant Vehicle No :	GBE9178L	Insured Vehicle No :	XE7421L
Date of Loss:	22/08/2022	Nature of Claim:	TP
		Claim No:	202222006278

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE9178L		
Make & Model:	TOYOTA HIACE, 3.0 D DX DIESEL TURBO MT 2WD	Engine No:	1KD2588738
	LGV (M)	Chassis No:	KDH2010189364
Reg. Date:	29/04/2016 (Man. Year: 2015)	Odometer:	183126 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	195 R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,659.87	3,800.37	859.50	18.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,680.00	1,500.00	47.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,839.87	5,480.37	2,359.50	30.10
Approved Total (Overridden) (\$\$)		4,300.00		
(\$\$)	7,839.87	4,300.00	3,539.87	45.15
+ GST 7.00/7.00% (\$\$)	548.79	301.00	247.79	45.15
Nett Amount (\$\$)	8,388.66	4,601.00	3,787.66	45.15
+ Loss of Use (4.0 x S\$100.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		5,003.00		

INSPECTION

Date of Assignment:	24/08/2022	
Date Inspected:	05/09/2022 Inspected At:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01- 2008/2010/2012 Singapore 489977
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 11 Nov 2022)	
Parts:	N/A	TOYOTA HIACE 3.0 D DX DIESEL TURBO MT 2WD LGV (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE9178L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDING DOOR LH	Dented / Bent	2,030.00 FL	*1,855.00 FL
2	1		*SLIDING DOOR GLASS LH	Shattered	839.00 FL	*620.10 FL
3	1		*SLIDING DOOR INNER LOCK LH	Not Necessary	270.10 FL	*- FL
4	1		*REAR FENDER GLASS LH	Shattered	839.00 FL	*685.00 FL
5	1		*REAR FENDER LH	Dented / Cracked	1,640.40 FL	*1,640.40 FL
6	4		*GLASS SEALANT	Necessary	96.00 FS	*80.00 FS
7	1		*SLIDING DOOR COMPANY STICKER LH	Necessary	350.00 FS	*120.00 FS
					Sub Total (\$\$)	6,064.50
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,404.63
					Total Parts (\$\$)	4,659.87

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	1,500.00	800.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	600.00
3	ANTI-RUST COATING	New	200.00	60.00
4	TO REMOVE & REFIT DOOR /FENDER GLASS	New	280.00	220.00
Gross Labour Cost (\$\$)			3,180.00	1,680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >