

# HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075  
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:  
Our Ref : 0765/08/22

Page: 2  
Date: 22/08/2022

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
	RH			
30	WEATHERSTRIP ASSY - FRONT DOOR BELT OUTSIDE, RH	1 @	53.00	53.00
31	BLACK TAPE - FRONT FOOR FRAME UPPER, RH	1 @	23.00	23.00
32	BLACK TAPE - FRONT DOOR REAR, RH	1 @	23.00	23.00
33	GUARD ASSY - FRONT WHEEL, LH	1 @	86.00	86.00
34	GUARD ASSY - FRONT WHEEL, RH	1 @	86.00	86.00
35	CLIP	20 @	4.90	98.00
36	RETAINER *SPECIAL NETT	10 @	4.90	49.00
37	FRONT RIM RH	1 @	697.00	697.00
38	FRONT BUMPER PLATE WITH CASING	1 @	35.00	35.00

## LABOUR CHARGES

1	REPLACE NEW PARTS, REMOVE / REFIT ALL	1,000.00
1	ATTACHMENT PARTS TO FACILITATE REPAIR	
1		
2	SPRAY PAINT ON THE EFFECTED AREAS	1,000.00
2	WITH 2K PAINT	
2		
3	CHECK WIRING AND PROPER FUNCTIONING	100.00

Nett Total Before GST

=====  
10,721.00  
=====

Yours faithfully,

  
\_\_\_\_\_  
(Workshop Manager)

# HIN LUNG WORKSHOP

Blk 1008 Bukit Merah Lane 3 #01-20, S'pore 159722. Tel: 68583000 Fax: 64760075  
Website: www.hinlung.com.sg GST Regn. No: M2-0065859-X

Your Ref:  
Our Ref : 0765/08/22  
M/s : LONPAC INSURANCE BHD  
300, BEACH ROAD #17-04/06 THE CONCOURSE  
SINGAPORE 199555

Page: 1  
Date: 22/08/2022

Attn : MOTOR CLAIM DEPARTMENT

Dear Sir/Madam,

ACCIDENT REPAIR ON : SMT2308R - AVANTE 1.6 GLS (A) 2020  
INSURED : BOLT CAR LEASING PTE LTD  
DATE OF ACCIDENT : 17/08/2022  
YOUR INSURED VEH NO: XD5101D

APPENDED BELOW ARE THE ESTIMATED COST OF REPAIR & PARTS TO BE REPLACED:-

		S\$	S\$	S\$
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER	1 @	475.00	475.00
2	MOULDING - FRONT BUMPER, LH	1 @	116.00	116.00
3	MOULDING - FRONT BUMPER, RH	1 @	116.00	116.00
4	LIP ASSY - FRONT BUMPER	1 @	64.00	64.00
5	CAP ASSY - FRONT BUMPER	1 @	18.00	18.00
6	BUMPER CLIPS	10 @	4.90	49.00
7	BRACKET - FRONT BUMPER SIDE LH	1 @	15.00	15.00
8	BRACKET - FRONT BUMPER SIDE RH	1 @	15.00	15.00
9	BRACKET ASSY - FRONT BUMPER UPPER SUPPORT, LH	1 @	15.00	15.00
10	BRACKET ASSY - FRONT BUMPER UPPER SUPPORT, RH	1 @	15.00	15.00
11	DUCT ASSY - AIR CURTAIN, LH	1 @	28.00	28.00
12	DUCT ASSY - AIR CURTAIN, RH	1 @	28.00	28.00
13	ABSORBER - FRONT BUMPER ENERGY	1 @	111.00	111.00
14	GRILLE ASSY - RADIATOR	1 @	530.00	530.00
15	COVER ASSY - RADIATOR GRILLE UPPER	1 @	85.00	85.00
16	STRIP - FRONT BUMPER	1 @	26.00	26.00
17	GRILLE - FRONT BUMPER SIDE, LH	1 @	34.00	34.00
18	GRILLE - FRONT BUMPER SIDE, RH	1 @	34.00	34.00
19	CLIP	10 @	4.90	49.00
20	MOULDING - FRONT BUMPER LICENSE PLATE	1 @	22.00	22.00
21	LAMP ASSY - FRONT TURN SIGNAL, LH	1 @	165.00	165.00
22	LAMP ASSY - FRONT TURN SIGNAL, RH	1 @	165.00	165.00
23	PANEL ASSY - UNDER COVER	1 @	134.00	134.00
24	CLIP	10 @	4.90	49.00
25	PANEL ASSY - HOOD	1 @	1,911.00	1,911.00
26	PANEL ASSY - FENDER, RH	1 @	1,227.00	1,227.00
27	LAMP ASSY - SIDE RETAINER, RH	1 @	28.00	28.00
28	PANEL ASSY - FRONT DOOR, RH	1 @	1,832.00	1,832.00
29	WEATHERSTRIP ASSY - FRONT DOOR SIDE,	1 @	115.00	115.00