



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

OPINION ON REPAIR COST FOR VEHICLE NO. SBS 7580Y

Qty	Description of Parts	Condition	Recommended (\$)
1	<u>REPLACEMENT OF PARTS</u>	CRACKED	
	30750005 = FRONT WINDSCREEN.UPP/S		1,235.00
			1,235.00
	<u>LABOUR</u>	NOT NECESSARY	
	LABOUR.		1,284.40
	SPRAY PAINTING. (NPA)		-
	VINYL. (NPA)	NOT NECESSARY	-
	ADVERTISEMENT.(NPA)	NOT NECESSARY	-
			1,284.40
GRAND TOTAL			2,519.40

RECOMMENDED COST OF REPAIRS (CONFIRMED)	2,519.40
--	-----------------

Report Ref No. CS/INC22008275/Rvy3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.