



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

Ref: CS/INC22008275/Rvy3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 16/09/2022

ATTN: DAVID PHUA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKU 3259K	Veh. Inspected	SBS 7580Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1185872-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	26/08/2022

2. Vehicle Particulars & Condition

Make & Model	VOLVO B9TL	c.c	9364
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	YV3S4P927BA143052	Colour	MULTI COLOUR
Odometer	744706 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
L/H Front Tyre	275/70 R22.5	BRIDGESTONE	8 mm
R/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm
L/H Rear Tyre	275/70 R22.5 (D)	BRIDGESTONE	8/8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	22/08/2022	Inspect Date / Time	29/08/2022 (09:09 AM)
Survey held at	SBS TRANSIT LTD (Branch) 28 SOON LEE ROAD SINGAPORE 628083		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------