

DATE: 31.08.2022  
DAY : Wednesday

**Workshop Accident Repair Estimate**  
**\*\*FOR SURVEYOR ONLY\*\***

ACCIDENT DATE	22.08.2022	BUS REGISTRATION NUMBER	SBS7580Y
ACCIDENT TIME	15:15 HRS	BUS TYPE (DD OR SD)	DD
THIRD PARTY CLAIM AGAINST	"UNKNOWN", PRIVATE CAR!	DATE of SURVEY	29.08.2022

S/No	SECTION A :	PARTS & MATERIAL COST	
	<b>SBS7580Y, Volvo B9TL Eu5, DD, AC, 3 Axle</b>		
	<b>Part or Item Description</b>	<b>Quantity</b>	<b>Total Cost</b>
1	30750005 = FRONT WINDSCREEN.UPP/S	1 pc	\$ 1,235.00
2	LAST ITEM		\$ -
3			\$ -
4			\$ -
5			\$ -
6			\$ -
7			\$ -
8			\$ -
9			\$ -
10			\$ -
11			\$ -
12			\$ -
13			\$ -
14			\$ -
15			\$ -
		<b>TOTAL PARTS &amp; MATERIAL COST</b>	<b>\$ 1,235.00</b>

	SECTION B:	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)	
	<b>FOR WORKSHOP ONLY.....</b>		
	<b>Labour</b>		<b>\$ 1,284.40</b>
	Spray Painting		\$ -
	Vinyl		\$ -
	Advertisement		\$ -
			\$ -
		<b>TOTAL LABOUR COST</b>	<b>\$ 1,284.40</b>

	SECTION C :	SUMMARY	
		<b>TOTAL REPAIR COSTS</b>	<b>\$ 2,519.40</b>
		<b>TOTAL DOWNTIME</b>	<b>1.0 day</b>

**NOTE:**

- 1) Repair cost is excluding Loss of use.
- 2) Additional parts might be required during the course of repair.